

Lawyers since 1897

Jo M. Flannery Attorney Of Counsel Ryan, Swanson & Cleveland, PLLC 1201 Third Avenue, Suite 3400 Seattle, WA 98101-3034 206.464.4224 | Fax: 206.583.0359

Toll-free: 1.800.458.5973 www.ryanswansonlaw.com

direct dial 206.654.2241 flannery@ryanlaw.com

Ref. No. 1875274.01/015435.00010

April 19, 2019

(VIA US MAIL AND EMAIL)

Michelle Mullin, Project Manager USEPA REGION 10 1200 Sixth Avenue Mail Code: OAW-150 Seattle, WA 98101 Mullin.michelle@Epamail.epa.gov

Re: Request for Modification to 12-18-2013 Risk Based Disposal Approval Supplement to Rainier Commons Phase I Close-Out Report

Dear Ms. Mullin,

As you know we represent Rainier Commons LLC. We write to provide substrate sampling documentation as a supplement to the Rainier Commons' Phase I Close-Out Report and in support of Rainier Commons' formal request to remove concrete and sandstone substrates from the Condition 8 requirements of the RBDA.

Enclosed please find two substrate sampling reports from NVL Labs, Inc., dated April 19, 2019. The first report addresses the concrete substrate. The second report addresses the sandstone substrate in the Phase I work areas. The sampling was performed following all Phase I paint removal work and full visual clearance. The sampling took into account and consideration all of the available concrete and sandstone areas. A grid system was applied to all of the Phase I concrete and sandstone areas. A random number generator was utilized to select the sampled locations. Three primary samples of each substrate type were collected along with a field duplicate and a split sample. The processes and procedures are detailed in the enclosed reports ensuring representative, quality controlled samples and results.

The sample results demonstrate three things:

- 1) The sample results demonstrate the effectiveness of the paint removal process in the general Work Plan;
- 2) The sample results further demonstrate that the PCBs in the dried applied paint did not migrate into the substrate; and

Charter Member of TAGLaw, a worldwide network of law firms

3) The sample results further demonstrate the reliability of the visual clearance protocol to clear and approve the work for unrestricted use, without the need for additional substrate sampling, or other work.

Condition 8 of the EPA's December 18, 2013 Risk Based Disposal Approval ("RBDA") provides as follows:

Rainier shall collect verification samples of concrete and any other substrate type not analyzed as part of the September 2011 RBDA (Enclosure 1, Reference 2) demonstration project [which removed brick and mortar from further need of substrate testing] once the visual standard for paint removal is met. Rainier shall use the grid system established in Condition 7 and collect a minimum of three samples per substrate, per phase of removal activity covered by the IPWP. As part of the IPWPs, Rainier shall devise a detailed sampling plan that will ensure that the data collected are representative of the PCBs that may remain in the substrate, and include an analysis of the representativeness in their sampling plan. The sampling plan shall also include sample collection methods, sample locations, and QA/QC. Sampling shall follow the guidelines provided in the EPA document titled 'Standard Operating Procedure For Sampling Porous Surfaces for Polychlorinated Biphenyls (PCBs)', revised May 5, 2011 (SOP). The most recent version can be found here:

http://www.epa.gov/regionl/cleanup/pcbs/pdfs/484692.pdf.

Data shall be sufficient for EPA to conclude that the visual performance standard is adequate to verify both removal of PCB bulk product waste and that no further cleanup is likely to be required for the remaining substrate to satisfy the performance criteria of 40 C.F.R. 761.6l(c) and 761.62(c) of no unreasonable risk of injury to health or the environment. If results of the sampling represent that the substrate presents no unreasonable risk of injury to health or the environment, Rainier may request a modification of this approval to eliminate the substrate sampling requirements.

Rainier Commons is submitting these substrate reports as a supplement to its Phase I Close-Out Report. The sampling plan, selection of locations, collection of samples, care, custody and transport of samples, laboratory analysis and reporting on the data was all conducted by NVL Labs. All of the sample results are below 1 ppm, which has been determined by EPA to be protective of human health and the environment and is consistent with unrestricted use. We trust this documentation will fulfill the final set of data required by EPA for full and final approval of the Phase I Close-Out Report.

In addition, the data provides the basis to remove the two additional substrate types, both concrete and sandstone, from further testing in future phases of work. Pursuant to the provision in Condition 8 of the RBDA set forth above, Rainier Commons formally requests the modification of Condition 8 of the RBDA adding Sandstone and Concrete to the Brick/Mortar substrate, which was previously cleared in 2011, to the list

of approved substrates, such that no further substrate testing will be required for these three substrate types.

We appreciate your immediate time and attention to this matter.

Very truly yours,

RYAN, SWANSON & CLEVELAND, PLLC

Jo M. Flannery Attorney Of Counsel

JMF:raw **Enclosures**

cc: Lynne D. Davies (via email - Davies.lynne@Epamail.epa.gov

Lisa McArthur - Manager, RCRA Corrective Action, Permits and PCB Unit (via email -

mcarthur.lisa@epa.gov) Dave Leonard, NVL

Phil Roberts

Client



April 19, 2019

Shimon Mizrahi Rainier Commons LLC 918 S. Horton Street, Suite 1018 Seattle, WA 98134

Subject: Polychlorinated Biphenyl (PCB) Substrate Testing

CONCRETE - POST VISUAL CLEARANCE

Site Address: Rainier Commons, LLC

3100 Airport Way S, Seattle, WA

NVL Project#: 2012-494

Dear Mr. Mizrahi:

Per your request, NVL Laboratories Inc. (NVL) tested concrete substrate, following final visual clearance and approval of paint removal work, for the presence of Polychlorinated Biphenyls (PCBs), at the Rainier Commons site per the conditions for such testing pursuant to Condition 8 of the EPA's December 18, 2013 Risk Based Disposal Approval for Rainier Commons. The purpose being to collect and provide data sufficient for the EPA to conclude that the visual performance standard is adequate to verify both removal of the PCB bulk waste and that when the visual clearance performance standard is met no further clean-up is likely required of the remaining substrate, with any remaining detectable levels of PCBs registering below the threshold for unrestricted use.

EXECUTIVE SUMMARY

Utilizing the "Sample Location Selection" process delineated in the Rainier Sampling Plan for Verification of Concrete Substrate Once Visual Clearance Standard Met (the NVL Substrate Sampling Plan), NVL randomly selected representative locations of the concrete substrate. These randomly selected locations were then tested for the presence of PCBs after all paint abatement work was completed and after all work areas were cleared utilizing the visual clearance performance standard and procedures.

Laboratory analysis of the concrete substrate did not detect the presence of PCBs with a Reporting Limit of less than 1 ppm. The results confirm that the visual clearance standards already approved for brick and mortar are also effective for concrete substrates. The results further confirm that PCBs contained in the historical layers of paint applied to the concrete did not migrate into the concrete substrate. These findings meet the requirements of Condition 8 of the EPA's Risk Based Disposal Approval (RBDA) for Rainier Commons.

Based on the findings, it is recommended that Rainier Commons request modification to the RBDA to eliminate concrete substrate sampling requirements, effective upon the completion of the Phase I work.

BACKGROUND

Condition 8 of the EPA's Risk Based Disposal Approval for Rainier Commons (RBDA) requires



testing of each type of substrate, from which historical layers of paint have been removed, to determine if PCBs contained in the paint migrated into the substrate, or remain at greater than 1 ppm following visual clearance pursuant to the visual clearance performance standards applicable to the work as set forth in Condition 7 of the RBDA and Exhibit 12 of the Phase I Individual Phased Work Plan (Phase I IPWP). Substrate test results confirm whether or not the visual clearance performance standard is sufficient to clear that particular type of substrate and can be relied upon, without further additional destructive substrate testing, to clear that particular type of substrate for unrestricted use. That is to say the substrate does not contain PCBs greater than 1 ppm.

The approved NVL Substrate Sampling Plan requires that a Certified Industrial Hygienist (CIH) oversee all sample collection, analysis, data interpretation and reporting with regards to substrate testing. After reviewing results for samples collected to date during the Phase I work on Buildings 10, 11 and 13, it became apparent that a CIH had not been involved in all aspects of all sample planning and collection events. The purpose of some Phase I samples previously collected was to assess abatement techniques and later collected samples were initially intended to serve as post-clearance samples. The timing of work performed, sample collection, punchlist work and the vernacular of "pre-clearance" and "post-clearance" samples apparently caused some confusion upon initial review of NVL's reporting on the laboratory results for these previously collected samples. Additionally, due to the piece meal approach in the initial series of sample collection events, the Field QA/QC procedures described in the NVL sampling plan were not adequately addressed. Given this, Rainier Commons determined to initiate the collection of a new concrete substrate sample set, commissioning NVL's CIH to prepare the sampling plan, oversee all sample location identification, collection, analysis, data interpretation and reporting, including all field QA/QC requirements. The body of this report provides the details of the concrete substrate sampling that was performed March 11, 2019 in response to this request.


Earlier sampling events – not included in this report but previously reported upon to EPA - and their purpose included the following:

- Rainer Commons requested the collection and analysis of concrete substrate samples from Building 13 on August 4, 2014 and Buildings 11 and 13 on September 29, 2014, prior to the visual clearance of the Phase I work, to measure the efficacy of initial sandblasting efforts. These informational pre-clearance samples were used to better understand the performance of the initial sandblasting techniques employed at that time and were not intended as "clearance" samples.
- On December 1, 2014 a concrete substrate sample was obtained by NVL Laboratory personnel for the purpose of addressing Condition 8 of the RBDA. Post clearance samples were also obtained in January 2015, July 2018, and September 2018. The field samples were obtained utilizing the "Sample Collection" section of the approved NVL Substrate Sampling Plan.
- During a subsequent desk review of the EPA SOP for Sampling Porous Surfaces for PCBs, it was noted that the document requires that the sampled area be cleaned with a clean brush or cloth prior to drilling (Section 9.1.1). This procedural step had been omitted in the NVL Substrate Sampling Plan. No specific annotation regarding proper sample site preparation was included in the field notes, therefore, it was concluded that areas where previous testing had identified the slight presence of PCBs, additional substrate sampling was warranted to ensure the required preparation step in the EPA SOP was performed.



SITE MAP

The circled area on this site map shows the locations of buildings 10, 11 and 13 at Rainier Commons.



METHOD

Field collection and subsequent laboratory analysis was performed in accordance with the NVL *Substrate Sampling Plan* (Exhibit 11 to Phase 1 IPWP), revised to include and match the EPA SOP. All concrete surfaces identified during the abatement process were equally included in the sample site selection process, making the three samples randomly selected fully representative of the total available sample population.

Details in NVL's Substrate Sampling Plan included:

- Having a Certified Industrial Hygienist (CIH) overseeing all sample collection, analysis, data interpretation and reporting involved with this assessment
- Specific procedures to randomly select sample testing locations
- Specific protocol for identifying the samples
- Specific instructions for sample collection
- Field QA/QC procedures, which included collecting field duplicate and split samples
- Specific requirements for the laboratories selected for sample analysis

The laboratories selected for sample analysis were:

- NVL Laboratories, Inc.
- Fremont Analytical Inc.

Both are accredited laboratories for analysis for PCB Aroclor content via EPA Method 8082. A Reporting Limit of less than 1 ppm was requested at the time of sample submission consistent with the requirements of the RBDA and unrestricted use.




TESTING


NVL, with Dave Leonard CIH on-site, conducted the testing on March 11, 2019 to test for PCBs. This substrate sampling was conducted following the conclusion of all Phase I work to remove PCB-containing paint coatings from the building and following the approval of all Phase I paint removal work by both NVL and the owner.

SAMPLE LOCATION SELECTION


The sample location selection protocol identified in NVL's *Substrate Sampling Plan* involved using a grid system. The following details how the grid pattern was established for Buildings 10, 11 and 13 where the concrete substrate was located.











Once the grid pattern and the 104 grid locations were identified, in order to define a smaller area to sample (the larger grid size being appropriate to the visual clearance sampling but not necessary or appropriate for gathering substrate material), the sampling grid was then further divided into four Grids (2.5' x 2.5') (Sub-Grids), and each of the Sub-Grids was again divided into four more smaller Grids (15"x15") (Sub-Sub-Grids).

The following table graphically shows how any Grid was further divided into a Sub-Grid and into a Sub-Sub-Grid along with numbering designation system:

1	Grid	Each = ~5' x ~5'			
2	Sub-Grid	Each = ~ 2.5' x ~2.5' Shown is the numbering designation system Highlighted is Sub-Grid #2	3	4	

Polychlorinated Biphenyl (PCB) Substrate Testing Project No. 2012-494

Page 6 / 12

CONCRETE - POST VISUAL CLEARANCE April 19, 2019



		Each = ~ 15" x ~15"		1	2	
3	Sub-Sub-Grid	Shown is the numbering designation system		3	4	
		Highlighted is Sub-Sub-Grid #1				
						<u>-</u> '

Once this grid pattern system was established, the three sampling locations were selected using the random number generator at www.random.org.

After the random selection of the three sampling locations, the selection of the location for duplicate and split samples was also performed using the random number generator at www.random.org.

The following summarizes the locations identified using the random number generator:

Sample Location	Grid	Sub-Grid	Sub-Sub-Grid	QC	QC
1	44	1 * 3	4	duplicate	split
2	62	1	3	-	-
3	72	3 ** 1	1	-	-

^{*=}For Grid location 44, Sub-Grid location 1 did not exist due to the fact that Sub-Grids 1 and 2 were on the brick surface. As a result, using the random number generator and selecting between Sub-Grids 3 and 4, Sub-Grid 3 was selected. The Sub-Sub-Grid location was kept since it was already selected by the random number generator.

Sample identification was also made per the protocols identified in NVL's *Substrate Sampling Plan* and are indicated as follows:

Sample	Sample Location	Grid	Sub Grid	Sub-Sub Grid	Sample Identification
1	1	44	1 * 3	4	31119-13EG-44
2	2	62	1	3	31119-13EG-62
3	3	72	3** 1	1	31119-13EG-72
4	1	44	1 * 3	4	31119-13EG-44-DUP
5	1	44	1 * 3	4	31119-13EG-44-SPLIT

Polychlorinated Biphenyl (PCB) Substrate Testing

Project No. 2012-494

CONCRETE - POST VISUAL CLEARANCE
April 19, 2019

^{**=} For Grid location 72, Sub-Grid location 3 did not exist due to the fact that this location was at the corner of the concrete and Sub-Grids 2, 3 and 4 were not on a concrete surface. As a result, only Sub-Grid 1 was valid. The Sub-Sub-Grid location was kept since it was already selected by the random number generator.



SAMPLE COLLECTION

Surface debris, if any, was removed using a clean brush and cloth as described in NVL's Substrate Sampling Plan prior to drilling.

Samples were collected using an impact hammer drill with a 5/8 inch concrete drill bit to generate a uniform, finely ground powder. Depth was controlled to be no more than one half inch by marking the depth with tape on the drill bit.

The drill bit was cleaned and decontaminated before use, and after each sample was obtained per the description in the sampling plan, which included scrubbing with water containing detergent, followed by rinsing with clean water and then rinsing/wiping the surface with hexane.

Clean, previously unused disposable gloves were used at each sample location.

Two holes needed to be drilled to obtain an approximated 10 grams of material per sample.

The split sample was collected at the same time as the original sample at that location. This was achieved by drilling four holes to generate approximately 20 grams of material that was then put into a single sample container. The closed sample container was then shaken to mix the sample and then half of the contents were then put into the "split" sample container leaving approximately 10 grams of material in each container.

The field duplicate sample was a separate sample collected as close as possible to the same point as the original sample at that location. Prior to the sample being collected, the same procedures for cleaning and decontaminating the drill bit were followed.

OBSERVATIONS

The following photographs note observations made when testing occurred on March 11, 2019.



Location 44-3-4

Samples collected at this location: 31119-13EG-44 31119-13EG-44-DUP 31119-13EG-44-SPLIT

Streaking on the concrete surface was caused by the application of a moss killer in 2018

Surface debris was removed using a clean brush and cloth prior to drilling.

The six holes at this location are the result of first drilling four holes to create ~20 grams of material to create split QA/QC samples. The second two holes were for collection of ~10 grams of material for the duplicate QA/QC sample.

Polychlorinated Biphenyl (PCB) Substrate Testing Project No. 2012-494

April 1

CONCRETE - POST VISUAL CLEARANCE

April 19, 2019



2



Location 62-1-3

Sample collected at this location: 31119-13EG-62

Two holes were drilled at this location to obtain ~10 grams of material for the single sample.

3



Location 72-1-1

Sample collected at this location: 31119-13EG-72

Two holes were drilled at this location to obtain ~10 grams of material for the single sample.

4



Concrete Drill Bit

Samples were collected using an impact hammer drill with a 5/8 inch concrete drill bit to generate a uniform, finely ground powder. Depth was controlled to be no more than one half inch by marking the depth with tape on the drill bit.

SAMPLE SUBMISSION

NVL maintained exclusive custody, control and security of samples collected and relinquished them to the selected laboratories for analysis using laboratory specific Chain of Custody (COC) forms that included fields for sample identification number, parameter for analyses, sample collection date and custody transfer signatures.

Per NVL's *Substrate Sampling Plan*, samples were submitted to accredited laboratories for analysis for PCB Aroclor content via EPA Method 8082. A Reporting Limit (RL) of less than 1 ppm was requested at the time of sample submission.

The laboratories selected for sample analysis were:

- NVL Laboratories, Inc.
- Fremont Analytical Inc.

Polychlorinated Biphenyl (PCB) Substrate Testing Project No. 2012-494

CONCRETE - POST VISUAL CLEARANCE April 19, 2019



RESULTS

The following table summarizes the results for concrete substrate testing:

CONCRETE SUBSTRATE TESTING RESULTS Sampling Date: 3/11/19									
Sample Identification	Sample Sample Grid Lab RL Lab RL					Result More Than 1 PPM?			
31119-13EG-44	SPLIT & DUP	NVL	44-3-4	0.40	ND	NO			
31119-13EG-44 SPLIT	SPLIT	F	44-3-4	0.804	ND	NO			
31119-13EG-44 DUP	DUP	NVL	44-3-4	0.39	ND	NO			
31119-13EG-62	-	NVL	62-1-3	0.39	ND	NO			
31119-13EG-72	-	NVL	72-1-1	0.39	ND	NO			

ND = Non-Detect

PPM = Parts per million or milligrams per kilogram (mg/kg)

Lab RL = Laboratory Reporting Limit

N = NVL Laboratories F = Fremont Analytical

DISCUSSION

Laboratory analysis did not detect any level of PCBs equal to or above 1 ppm in any of the samples. All samples were run with a reporting limit of less than 1 ppm. All sample results were below the requirement for unrestricted use.

Field QA/QC Procedures

Field Duplicate Samples:

- Reproducibility and representativeness of the samples was confirmed with the results of
 the field duplicate samples. The field duplicate samples were separate samples
 collected as close as possible to the same sample location and analyzed by the same
 laboratory (NVL). Analysis results for both duplicate samples did not detect the
 presence of PCBs with a reporting limit of less than 1 ppm. This meets the QA/QC
 requirement that laboratory analysis results must be within 75 to 125 percent of each
 other to be acceptable.
- A duplicate sample was taken at one of the three testing locations. In other words, 33% of the three samples taken from the three locations had a "field duplicate" which meets the QA/QC procedure criteria that a minimum of 10% of the sample set be field duplicates.



Split Samples:

- Accuracy and reproducibility of the analytical results was confirmed by the split samples.
 The analytical results of splitting a sample and having it analyzed at two separate
 laboratories (NVL Laboratories and Fremont Analytical) did not detect the presence of
 PCBs with a reporting limit of less than 1 ppm. This meets the QA/QC requirement that
 laboratory analysis results must be within 75 to 125 percent of each other for the split
 sample results to be acceptable.
- One sample from the three sample locations was identified as a Split Sample that was submitted to another laboratory for analysis. This is 33% of the sample locations and 25% of the 4 samples submitted to the same laboratory, which meets the QA/QC procedure criteria that a minimum of 5% of the sample set be split samples.

Laboratory QA/QC Procedures

 Both NVL Laboratories and Fremont Analytical followed the QA/QC procedures that are requirements of NVL's Substrate Sampling Plan which include the addition of surrogates, laboratory control sample (LCS) and LCS duplicate, matrix spike (MS) and MS duplicate and continuous calibration check (CCV) sample for all PCB analysis. All results of QA/QC procedures were within analytical protocols. Copies of the laboratory analysis are included with this report which details the QA/QC information.

CONCLUSION

Sample selection was representative of the population in that all concrete substrate was equally considered during the random selection process. Testing of the concrete substrate did not detect the presence of PCBs with a Reporting Limit of less than 1 ppm. The findings confirm that the visual clearance standards approved for brick and mortar are also reliable to confirm and approve removal of paint from concrete substrates and that PCBs contained in the historical layers of paint applied to the concrete did not migrate into the concrete substrate. These findings meet the requirements of Condition 8 of the EPA's Risk Based Work Plan Approval (RBDA) for Rainier Commons. As a result, it is recommended that Rainier Commons request modification to the RBDA to eliminate concrete substrate sampling requirements, effective as of the completion of Phase I.

Reviewed by:

Testing & Assessment Overseen by:

Munaf Khan Project Manager

Laboratory Director / President

David Leonard MSPH, CIH Certified Industrial Hygienist Technical Resource Expert



ATTACHMENTS

Laboratory Testing Reports:

- NVL Laboratories Inc. Batch Number 1904660
- Fremont Analytical Inc. Analytical Report Work Order Number 1903135

REFERENCED

- Condition 8 of the EPA's December 18, 2013 Risk Based Disposal Approval for Rainier Commons (RBDA)
- NVL Substrate Sampling Plan (Exhibit 11 to Phase 1 IPWP), revised to include and match the EPA SOP.
- Exhibit 12 of the Phase I Individual Phased Work Plan (Phase I IPWP)
- Visual clearance standards required in Condition 7 of the RBDA and Exhibit 12 of the Phase IIPWP

March 13, 2019



Mr. Marcus Gladden NVL Field Services Division 4708 Aurora Ave. N. Seattle, 98103

Re: NVL Batch 1904660.00

Project Name/Number: 2019-494

Project location: 3100 Airport Way South Seattle, WA 98134

Dear Mr. Gladden,

Enclosed please find test results for samples submitted to our laboratory for analysis. Preparation and analysis of these samples were conducted in accordance with published industry standards and methods specified on the attached analytical report.

The content of this package consists of the following:

- -Case Narrative & Definition of Data Qualifiers
- -Analytical Test Results
- -Applicable QC Summary
- -Client Chain-of-Custody (CoC)
- -NVL Receiving Record

The report is considered highly confidential and will not be released without your approval. Samples are archived for two weeks following analysis. Samples that are not retrieved by the client will be discarded after two weeks.

Thank you for using our laboratory services. If you need further assistance, please contact us at 206-547-0100 or 1-888-NVLLABS.

Sincerely,

Nick Ly, Technical Director

Enclosure: Sample Results



Case Narrative:

The following summarizes samples received on date as shown on the accompanied Chain of custody by NVL Laboratories, Inc. from NVL Laboratories, Inc. for Project Number: 2019-494. Samples were logged in for PCB analysis per client request using both customer sample ID's and laboratory assigned ID's as listed on the Chain-of-Custody (CoC). All samples as received were processed and analyzed within specified turnaround time without any abnormalities and deviations that may affect the analytical results. All quality control requirements were acceptable unless stated otherwise. The conditions of all samples were acceptable at time of receipt and all samples submitted with this batch were analyzed unless stated otherwise on the CoC.

Test Results are reported based on dry weight in milligrams per kilograms (mg/kg) for PCB samples as shown on the analytical reports.



Definition Appendix

Terms

% Rec	Percent recovery.
<	Below Reporting Limit(RL) or Limit of Quantitation(LoQ) of the instrument.
В	Blank contamination. The recorded results is associated with a contaminated blank.
DF	Dilution Factor
J	The reported concentration is an estimated value because something may be present in the sample that interfered with the analysis.
J1	The reported concentration is an estimated value because the laboratory control sample (LCS) is out of control limits.
J2	The reported concentration is an estimated value because the percent recovery for matrix spike is out of control limits.
J3	The reported concentration is an estimated value because the relative percent difference(RPD) for duplicate analysis is out of control limits.
J4	Percent recovery is outside of established control limits.
LCS	Laboratory Control Sample.
LFS	Laboratory Fortified Spike
Limits	The upper and lower control limits for spike recoveries.
LN	Quality control sample is outside of control limits. This analyte was not detected in the sample.
LOQ	Limit of quantitation(same as RL)
mg/kg	Milligrams per kilogram.
ND	Analyte not detected or below the reporting limit of the instrument or methodology



Definition Appendix

Terms

PPM Parts per Million.

QC Batch Group Quality Control Batch Group. The entity that links analytical results

and supporting quality control results.

R The data are not reliable due to possible contamination or loss of

material during preparation or analysis. Re-sampling and reanalysis

are necessary for verification.

RL Reporting Limit. The minimum concentration that can be quantified

under routine operating conditions.

RPD Relative Percent Difference. The relative difference between

duplicate results(matrix spike, blank spike, or samples duplicate)

expressed as a percentage.

RPD Limit The maximum RPD allowed for a set of duplicate

measurements(see RPD).

SMI Surrogate has matrix interference.

Spike Conc. The measured concentration, in sample basis units, of a spiked

sample.

SURR-ND Surrogate was not detected due to matrix interference or dilution.

ug/m3 Micrograms per cubic meter.

ug/mL Micrograms per milliliter

mg/Kg milligram per kilogram

ANALYSIS REPORT



Polychlorinated Biphenyls by Gas Chromatography

Client NVL Field Services Division

SDG Number 1904660.00

Date Reported **03/13/2019**

Project Number 2019-494

Location 3100 Airport Way South Seattle, WA 98134

Samples Received*

Analyzed By

Aaron Brown

Samples Analyzed*

0000

Analysis Method

8082A

Preparation Method 3546PR (PCB)

* for this test only

Sample Number	31119-13EG-44	Received	03/11/2019
Lab Sample ID	19024136	Matrix	Material
Initial Sample Size	5.0241 gm	Units of Result	mg/Kg, as received

Analyte	RL	Final Result	Analysis Date
Aroclor-1016	0.40	< 0.40	03/12/2019
Aroclor-1221	0.40	< 0.40	03/12/2019
Aroclor-1232	0.40	< 0.40	03/12/2019
Aroclor-1242	0.40	< 0.40	03/12/2019
Aroclor-1248	0.40	< 0.40	03/12/2019
Aroclor-1254	0.40	< 0.40	03/12/2019
Aroclor-1260	0.40	< 0.40	03/12/2019
PCBs, Total	0.40	<0.4	

Sample Number	31119-13EG-44DUP	Received	03/11/2019
Lab Sample ID	19024137	Matrix	Material
Initial Sample Size	5.1547 gm	Units of Result	mg/Kg, as received

Analyte	RL	Final Result	Analysis Date
Aroclor-1016	0.39	< 0.39	03/12/2019
Aroclor-1221	0.39	< 0.39	03/12/2019
Aroclor-1232	0.39	< 0.39	03/12/2019
Aroclor-1242	0.39	< 0.39	03/12/2019
Aroclor-1248	0.39	< 0.39	03/12/2019
Aroclor-1254	0.39	< 0.39	03/12/2019
Aroclor-1260	0.39	< 0.39	03/12/2019
PCBs, Total	0.39	<0.39	

ANALYSIS REPORT



Polychlorinated Biphenyls by Gas Chromatography

Sample Number	31119-13EG-62	Received	03/11/2019
Lab Sample ID	19024138	Matrix	Material
Initial Sample Size	5.1491 gm	Units of Result	mg/Kg, as received
Analyte		RL	Final Result Analysis Date
Aroclor-1016		0.39	< 0.39 03/12/2019
Aroclor-1221		0.39	< 0.39 03/12/2019
Aroclor-1232		0.39	< 0.39 03/12/2019
Aroclor-1242		0.39	< 0.39 03/12/2019
Aroclor-1248		0.39	< 0.39 03/12/2019
Aroclor-1254		0.39	< 0.39 03/12/2019
Aroclor-1260		0.39	< 0.39 03/12/2019
PCBs, Total		0.39	<0.39
Sample Number	31119-13EG-72	Received	03/11/2019
Lab Sample ID	19024139	Matrix	Material
Initial Sample Size	5.1472 gm	Units of Result	mg/Kg, as received
	5.1472 gm	Units of Result	mg/Kg, as received Final Result Analysis Date
Analyte	5.1472 gm		
Analyte Aroclor-1016	5.1472 gm	RL	Final Result Analysis Date
Initial Sample Size Analyte Aroclor-1016 Aroclor-1221 Aroclor-1232	5.1472 gm	RL 0.39	Final Result Analysis Date < 0.39 03/12/2019
Analyte Aroclor-1016 Aroclor-1221 Aroclor-1232	5.1472 gm	RL 0.39 0.39	Final Result Analysis Date < 0.39 03/12/2019 < 0.39 03/12/2019
Analyte Aroclor-1016 Aroclor-1221 Aroclor-1232 Aroclor-1242	5.1472 gm	RL 0.39 0.39 0.39	Final Result Analysis Date < 0.39 03/12/2019 < 0.39 03/12/2019 < 0.39 03/12/2019
Analyte Aroclor-1016 Aroclor-1221 Aroclor-1232 Aroclor-1242 Aroclor-1248	5.1472 gm	RL 0.39 0.39 0.39 0.39	Final Result Analysis Date < 0.39 03/12/2019 < 0.39 03/12/2019 < 0.39 03/12/2019 < 0.39 03/12/2019
Analyte Aroclor-1016 Aroclor-1221	5.1472 gm	RL 0.39 0.39 0.39 0.39 0.39	Final Result Analysis Date < 0.39 03/12/2019 < 0.39 03/12/2019 < 0.39 03/12/2019 < 0.39 03/12/2019 < 0.39 03/12/2019 < 0.39 03/12/2019



Quality Control Results

Project Number:	2019-494			Number: ct Manager:		1904660 Marcus Gl				
QC Batch(es): QC Batch Method:	Q910 3546PR (PCB)			Analy Analysis D	sis Method: escription:	80 8 Pol		ed Bipl	nenyls by Ga	s
Preparation Date:	03/12/2019					Chi	romatogra	phy		
Blank: MBLK-19046	60									
A I . t .	Blank				RL		Control			0
Analyte	Result	Units	DF		4.0		Limit			Qualifiers
Aroclor-1016	ND	mg/Kg	1		1.0		1			
Aroclor-1221	ND	mg/Kg	1		1.0		1			
Aroclor-1232	ND	mg/Kg	1		1.0		1			
Aroclor-1242	ND	mg/Kg	1		1.0		1			
Aroclor-1248	ND	mg/Kg	1		1.0		1			
Aroclor-1254	ND	mg/Kg	1		1.0		1			
Aroclor-1260	ND	mg/Kg	1		1.0		1			
PCBs, Total	ND	mg/Kg	1		1.0		1			
Surrogates:						% Rec				
Tetrachloro-m-xylene			1			75	40-140			
Decachlorobiphenyl			1			90	40-140			
Lab Control Sample:		60								
A 1.	Blank Spike			Spike		0/ 5	% Rec			0 ""
Analyte	Result	Units	DF	Conc.		% Rec	Limits			Qualifiers
Aroclor-1254 Surrogates:	17.4	mg/Kg	1	20.0		87	40-140			
Tetrachloro-m-xylene			1			73	40-140			
Decachlorobiphenyl			1			92	40-140			
Lab Control Sample:	: LCS-1016-1260-	1904660								
Lab Control Sample	Duplicate: LCSD-	1016-1260	-1904660							
	Blank Spike			Spike						
Analyte	Result	Units	DF	Conc.		% Rec	Limits	RPD	RPD Limit	Qualifiers
Aroclor-1016	15.5	mg/Kg	1	20.0		78	40-140			
	14.9			20.0		74	40-140	4	50	
Aroclor-1260	20.7	mg/Kg	1	20.0		104	40-140			
0	20			20.0		100	40-140	4	50	
Surrogates:										
Tetrachloro-m-xylene			1			71	40-140			
Danashlandiili			4			66	40-140			
Decachlorobiphenyl			1			94	40-140			
						91	40-140			



Surrogate Recovery Summary Report

Client NVL Field Services Divisi	<u>on</u>	SDG Num	nber <u>1904660</u>	
Project 2019-494				
Customer Sample ID	Lab Sample ID	Analyte	Recovery	Limits
31119-13EG-44	19024136	Decachlorobiphenyl	88%	40-140
31119-13EG-44	19024136	Tetrachloro-m-xylene	72%	40-140
31119-13EG-44DUP	19024137	Decachlorobiphenyl	89%	40-140
31119-13EG-44DUP	19024137	Tetrachloro-m-xylene	72%	40-140
31119-13EG-62	19024138	Decachlorobiphenyl	82%	40-140
31119-13EG-62	19024138	Tetrachloro-m-xylene	51%	40-140
31119-13EG-72	19024139	Decachlorobiphenyl	70%	40-140
31119-13EG-72	19024139	Tetrachloro-m-xylene	47%	40-140
LCS-1016-1260-1904660	LCS-1016-1260-1904660	Decachlorobiphenyl	94%	40-140
LCS-1016-1260-1904660	LCS-1016-1260-1904660	Tetrachloro-m-xylene	71%	40-140
LCS-1254-1904660	LCS-1254-1904660	Decachlorobiphenyl	92%	40-140
LCS-1254-1904660	LCS-1254-1904660	Tetrachloro-m-xylene	73%	40-140
LCSD-1016-1260-1904660	LCSD-1016-1260-1904660	Decachlorobiphenyl	91%	40-140
LCSD-1016-1260-1904660	LCSD-1016-1260-1904660	Tetrachloro-m-xylene	66%	40-140
MBLK-1904660	MBLK-1904660	Decachlorobiphenyl	90%	40-140
MBLK-1904660	MBLK-1904660	Tetrachloro-m-xylene	75%	40-140

^{*} Recovery outside limits



INITIAL AND CONTINUING CALIBRATION VERIFICATION

SDG No: <u>1904660</u> Contract:

Determination: 8082 PCB Aroclors < Material>

Run	Sample	Source	Analyzed	Analyte	True	Found	Unit	% Rec	Limits
R000903	CCV1-1016- 1260	PCB_2017-1-2	03/12/2019	Aroclor-1016	5	5	ug/mL	100	80-120
		PCB_2017-1-2	03/12/2019	Aroclor-1260	5	5	ug/mL	100	80-120
	CCV1-1254	PCB_2017-1-3	03/12/2019	Aroclor-1254	5	5	ug/mL	100	80-120
	ICV 1016-1254- 1260	PCB_2017-1-4	03/12/2019	Aroclor-1016	5	5.363	ug/mL	107	85-115
		PCB_2017-1-4	03/12/2019	Aroclor-1254	5	5.526	ug/mL	111	85-115
		PCB_2017-1-4	03/12/2019	Aroclor-1260	5	5.703	ug/mL	114	85-115
	CCV2-1016- 1260	PCB_2017-1-2	03/12/2019	Aroclor-1016	5	4.951	ug/mL	99	80-120
		PCB_2017-1-2	03/12/2019	Aroclor-1260	5	5.392	ug/mL	108	80-120
	CCV2-1254	PCB_2017-1-3	03/12/2019	Aroclor-1254	5	5.224	ug/mL	104	80-120

% Rec = Percent recovery

FORM PAS-RSR-1.1 Date Printed: 3/13/2019 9:24 Page 1 of 1

^{* =} Percent recovery not within control limits

ORGANICS LABORATORY SERVICES

		NVL Field Services Divis 4708 Aurora Ave. N. Seattle, WA 98103	TAT 2 Days AH No Rush TAT	
Proje	Phone	Mr. Marcus Gladden (206) 547-0100 (b) (6)	Due Date 3/13/2019 Time 3:50 PM Email marcus.g@nvllabs.com Fax (206) 634-1936	
Proj	ect Name/N	lumber: 2019-494	Project Location: 3100 Airport Way South Seattle, WA 98134	
Ite	m Code OR	antitative analysis RG-05 Me er of Samples 4	ethod 8082 PCB Aroclors <bulk></bulk>	
	Lab ID	Sample ID		
1	19024136	31119-13EG-44	Description	A/R A
2	19024137	31119-13EG-44DUP		A
3	19024138	31119-13EG-62		A

	Print Name	Signature	Company	Date	Time
Sampled by	Client				
Relinquished by	Client				
Office Use Only	Print Name	Signature	Company	Date	Time
Received by	Kaiser Wiggins		NVL	3/11/19	1550
Analyzed by	Am Bum	1	NVL	3/12/19	14:00
Results Called by		10			
Faxed Emailed					
Special Instructions:					

Entered By: Kaiser Wiggins

4 19024139

31119-13EG-72

Date: 3/11/2019

Time: 6:04 PM

1 of 1

Page 10 of 11

4706 Aurora Ave North Seattle, WA 98103 p 205 547 0100 | £206 634 1936 | www.mxllabs.com

NVL Laboratories, Inc. 4708 Aurora Ave N, Seattle, WA 98103

CHAIN of CUSTOD SAMPLE LOG

1904660



p 206.547.0100	f 206.634.1936	6 www.nvllabs.co	m	SAM		3		A 5
Clie	nt NVL Lab	oratories Inc			NVL Batcl			
	et 4708 Aur				Client Jol	Number 2012-494	×	
	-	VA 98103			Total	Samples		
Project Manag	er Munaf Kh	nan			Turn Arou	nd Time 🗌 1 Hr 🔲 6 Hrs	s 🗌 3 Days [] 10 Days
		oort Way South				☐ 2 Hrs ☐ 1 Da	ıy ☐ 4 Days ıvs ☐ 5 Davs	9
-		VA 98134					l for TAT less than	1 24 Hrs
					Emai	l address		
F	ie: (206) 447		(206) 44			_		
Asbestos		/ (NIOSH 7400)	☐ TEM (NIOSH 7402)	TEM (A	HERA) 🗌 TEM (EPA Le	evel II) 🔲 Othe)r
Asbestos	Bulk PLM	1 (EPA/600/R-93/	116) 🔲 F	PLM (EPA Poi	nt Count)	PLM (EPA Gravimetry)	TEM BULK	
Mold/Fun	gus 🔲 Mold	d Air 🗌 Mold Bu	ılk 📗 I	Rotometer Ca	libration			er Metals
METALS Total Meta TCLP Cr 6 Other Typ of Analysi	ICP GFA	A (ppm) Air F (ppm) Drink AA (ppb) Dust rglass Nuisa	ilter king water /wipe (Are nce Dust rable Dust	a) ☐ Paint 0	hips in %	Barium (Ba) Lead Cadmium (Cd) Merd	omium (Cr d (Pb) curv (Ha)	All 3 opper (Cu) ickel (Ni) inc (Zn)
Condition of	Package:	Good 🗌 Dama	aged (no s	pillage) 🗌 S	evere damag	e (spillage)		
Seq. # La	b ID	Client Sample	e Number	Comments				A/R
1		31119-1366	-44	BLOG 13	EAST E	LEV. GROUND #	144-3-4 5	
2		31119 -1366-					4-3-4 Fee	STREET, STREET
3		31114 -13EG	62			U-GROUND # 62		-
4		BII19 -13EG -		BLOB 13	EAST ELE	1- GROWND # 72	-1-1	
5								
6								
7								
8	tt.							
9								
10								
11								
12								
13								
14		_						
15								
	Print E		Cian Dat	. /		(No program)		Marketon Marketon
Sampl		LEONARD	Sian Belo	JV _		NVL LABS	3/11/19	Time 9:30
Relinquish		Trowns	-	1	A	IVUL LAND	3/14/1	15:45
Receiv		Mere	Ve	ue(1)		NUL Leibs	7-11-19	1550
Analyz		~ Bron	1			Nn	3/12/19	14:00
Results Cali	2014	, Dian		1		1000	7/12/17	.1.00
Results Fax								
Special Insti	COLUMN TO THE REAL PROPERTY.	nless requested in	n writing, a	all samples wi	ll be disposed	d of two (2) weeks after ar	nalysis.	



3600 Fremont Ave. N.
Seattle, WA 98103
T: (206) 352-3790
F: (206) 352-7178
info@fremontanalytical.com

NVL Labs, Inc. Marcus Gladden 4708 Aurora Ave. N. Seattle, WA 98103

RE: Rainier Commons

Work Order Number: 1903135

March 13, 2019

Attention Marcus Gladden:

Fremont Analytical, Inc. received 1 sample(s) on 3/11/2019 for the analyses presented in the following report.

Polychlorinated Biphenyls (PCB) by EPA 8082 Sample Moisture (Percent Moisture)

This report consists of the following:

- Case Narrative
- Analytical Results
- Applicable Quality Control Summary Reports
- Chain of Custody

All analyses were performed consistent with the Quality Assurance program of Fremont Analytical, Inc. Please contact the laboratory if you should have any questions about the results.

Thank you for using Fremont Analytical.

Sincerely,

Mike Ridgeway Laboratory Director

DoD/ELAP Certification #L17-135, ISO/IEC 17025:2005 ORELAP Certification: WA 100009-007 (NELAP Recognized)

RCLLC 0006970



Date: 03/13/2019

CLIENT: NVL Labs, Inc. Work Order Sample Summary

Project: Rainier Commons

Work Order: 1903135

Lab Sample ID Client Sample ID Date/Time Collected Date/Time Received

1903135-001 31119-13EG-44SPLIT 03/11/2019 9:30 AM 03/11/2019 4:45 PM



Case Narrative

WO#: **1903135**Date: **3/13/2019**

CLIENT: NVL Labs, Inc.

Project: Rainier Commons

WorkOrder Narrative:

I. SAMPLE RECEIPT:

Samples receipt information is recorded on the attached Sample Receipt Checklist.

II. GENERAL REPORTING COMMENTS:

Results are reported on a wet weight basis unless dry-weight correction is denoted in the units field on the analytical report ("mg/kg-dry" or "ug/kg-dry").

The validity of the analytical procedures for which data is reported in this analytical report is determined by the Laboratory Control Sample (LCS) and the Method Blank (MB). The LCS and the MB are processed with the samples to ensure method criteria are achieved throughout the entire analytical process.

III. ANALYSES AND EXCEPTIONS:

Exceptions associated with this report will be footnoted in the analytical results page(s) or the quality control summary page(s) and/or noted below.

Prep Sample Cleanup Comments:

1903135-001A 320023 Acid: Prep Comments for METHOD (PREP-PCB-S), SAMPLE (1903135-001A) required Acid Cleanup Procedure (Using Method No 3665A).

1903135-001A 320023 Florisil: Prep Comments for METHOD (PREP-PCB-S), SAMPLE (1903135-001A) required Florisil Cleanup Procedure (Using Method No 3620C).



Qualifiers & Acronyms

WO#: **1903135**

Date Reported: 3/13/2019

Qualifiers:

- * Flagged value is not within established control limits
- B Analyte detected in the associated Method Blank
- D Dilution was required
- E Value above quantitation range
- H Holding times for preparation or analysis exceeded
- I Analyte with an internal standard that does not meet established acceptance criteria
- J Analyte detected below Reporting Limit
- N Tentatively Identified Compound (TIC)
- Q Analyte with an initial or continuing calibration that does not meet established acceptance criteria (<20%RSD, <20% Drift or minimum RRF)
- S Spike recovery outside accepted recovery limits
- ND Not detected at the Reporting Limit
- R High relative percent difference observed

Acronyms:

%Rec - Percent Recovery

CCB - Continued Calibration Blank

CCV - Continued Calibration Verification

DF - Dilution Factor

HEM - Hexane Extractable Material

ICV - Initial Calibration Verification

LCS/LCSD - Laboratory Control Sample / Laboratory Control Sample Duplicate

MB or MBLANK - Method Blank

MDL - Method Detection Limit

MS/MSD - Matrix Spike / Matrix Spike Duplicate

PDS - Post Digestion Spike

Ref Val - Reference Value

RL - Reporting Limit

RPD - Relative Percent Difference

SD - Serial Dilution

SGT - Silica Gel Treatment

SPK - Spike

Surr - Surrogate

Original



Analytical Report

Work Order: **1903135**Date Reported: **3/13/2019**


Client: NVL Labs, Inc. Collection Date: 3/11/2019 9:30:00 AM

Project: Rainier Commons **Lab ID:** 1903135-001

Matrix: Solid

Client Sample ID: 31119-13EG-44SPLIT

Analyses	Result	RL	Qual	Units	DF	- Da	ate Analyzed	
Polychlorinated Biphenyls (PC	B) by EPA 8082	2		Batch	ı ID:	23788	Analyst: SB	
Aroclor 1016	ND	0.804		mg/Kg-dry	1	3/13	/2019 11:13:03 AM	
Aroclor 1221	ND	0.804		mg/Kg-dry	1	3/13	/2019 11:13:03 AM	
Aroclor 1232	ND	0.804		mg/Kg-dry	1	3/13	/2019 11:13:03 AM	
Aroclor 1242	ND	0.804		mg/Kg-dry	1	3/13	/2019 11:13:03 AM	
Aroclor 1248	ND	0.804		mg/Kg-dry	1	3/13	/2019 11:13:03 AM	
Aroclor 1254	ND	0.804		mg/Kg-dry	1	3/13	/2019 11:13:03 AM	
Aroclor 1260	ND	0.804		mg/Kg-dry	1	3/13	/2019 11:13:03 AM	
Aroclor 1262	ND	0.804		mg/Kg-dry	1	3/13	/2019 11:13:03 AM	
Aroclor 1268	ND	0.804		mg/Kg-dry	1	3/13	/2019 11:13:03 AM	
Total PCBs	ND	0.804		mg/Kg-dry	1	3/13	/2019 11:13:03 AM	
Surr: Decachlorobiphenyl	85.6	30.8 - 168		%Rec	1	3/13	/2019 11:13:03 AM	
Surr: Tetrachloro-m-xylene	114	30.3 - 157		%Rec	1	3/13	/2019 11:13:03 AM	
Sample Moisture (Percent Mois	sture)			Batch	ID:	R49992	Analyst: EAS	
Percent Moisture	5.75	0.500		wt%	1	3/13	/2019 10:13:58 AM	





Work Order: 1903135

QC SUMMARY REPORT

CLIENT: NVL Labs, Inc. Project: Rainier Commons

Polychlorinated Biphenyls (PCB) by EPA 8082

Project: Rainier Co	mmons							<u> </u>			
Sample ID MB-23788	SampType: MBLK			Units: mg/Kg		Prep Dat	e: 3/12/2 0)19	RunNo: 500	003	
Client ID: MBLKS	Batch ID: 23788					Analysis Dat	e: 3/13/2 0)19	SeqNo: 981	1235	
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qua
Aroclor 1016	ND	0.100									
Aroclor 1221	ND	0.100									
Aroclor 1232	ND	0.100									
Aroclor 1242	ND	0.100									
Aroclor 1248	ND	0.100									
Aroclor 1254	ND	0.100									
Aroclor 1260	ND	0.100									
Aroclor 1262	ND	0.100									
Aroclor 1268	ND	0.100									
Total PCBs	ND	0.100									
Surr: Decachlorobiphenyl	64.4		50.00		129	30.8	168				
Surr: Tetrachloro-m-xylene	62.2		50.00		124	30.3	157				
Sample ID LCS1-23788	SampType: LCS			Units: mg/Kg		Prep Dat	e: 3/12/2 0)19	RunNo: 500	003	
Client ID: LCSS	Batch ID: 23788					Analysis Dat	e: 3/13/2 0)19	SeqNo: 981	1236	
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qua
Aroclor 1016	1.08	0.100	1.000	0	108	38.5	149				
Aroclor 1260	1.03	0.100	1.000	0	103	35.4	154				
Surr: Decachlorobiphenyl	56.2		50.00		112	30.8	168				
Surr: Tetrachloro-m-xylene	61.6		50.00		123	30.3	157				
Sample ID LCS1D-23788	SampType: LCSD			Units: mg/Kg		Prep Dat	e: 3/12/2 0)19	RunNo: 500	003	
Client ID: LCSS02	Batch ID: 23788					Analysis Dat	e: 3/13/2 0)19	SeqNo: 981	1237	
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qua
Aroclor 1016	0.848	0.100	1.000	0	84.8	38.5	149	1.077	23.8	20	R
Aroclor 1260	0.738	0.100	1.000	0	73.8	35.4	154	1.034	33.4	20	R
									_		
Surr: Decachlorobiphenyl	40.2		50.00		80.3	30.8	168		0		

Original Page 6 of 10



Date: 3/13/2019

Work Order: 1903135

QC SUMMARY REPORT

CLIENT: NVL Labs, Inc.

Polychlorinated Biphenyls (PCB) by EPA 8082

Sample ID LCS1D-23788 SampType: LCSD Units: mg/Kg Prep Date: 3/12/2019 RunNo: 50003

Client ID: LCSS02 Batch ID: 23788 Analysis Date: 3/13/2019 SeqNo: 981237

Analyte Result RL SPK value SPK Ref Val %REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

NOTES:

Project:

R - High RPD observed, spike recoveries are within range.

Rainier Commons

Sample ID LCS2-23788	SampType: LCS			Units: mg/Kg)19	RunNo: 50003					
Client ID: LCSS	Batch ID: 23788)19	SeqNo: 981238					
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Aroclor 1254	1.03	0.100	1.000	0	103	31.9	167				
Surr: Decachlorobiphenyl	46.3		50.00		92.6	30.8	168				
Surr: Tetrachloro-m-xylene	55.9		50.00		112	30.3	157				



Rainier Commons

Date: 3/13/2019

Work Order: 1903135

Project:

QC SUMMARY REPORT

CLIENT: NVL Labs, Inc.

Sample Moisture (Percent Moisture)

Sample ID 1903157-007ADUP	SampType: DUP	Units: wt%	Prep Date: 3/13/2019	RunNo: 49992
---------------------------	----------------------	------------	----------------------	--------------

Client ID: **BATCH** Batch ID: **R49992** Analysis Date: **3/13/2019** SeqNo: **980950**

Analyte Result RL SPK value SPK Ref Val %REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Percent Moisture 8.23 0.500 8.609 4.56 20

Sample ID 1903155-001ADUP SampType: **DUP** Units: wt% Prep Date: 3/13/2019 RunNo: 49992 Client ID: BATCH Batch ID: **R49992** Analysis Date: 3/13/2019 SeqNo: 980953 SPK value SPK Ref Val Analyte Result RL %REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Percent Moisture 12.1 0.500 12.45 3.15 20

Original Page 8 of 10



Sample Log-In Check List

C	lient Name:	NVL	Work Order Numb	er: 1903135	
Lo	ogged by:	Brianna Barnes	Date Received:	3/11/201	9 4:45:00 PM
<u>Cha</u>	in of Cust	<u>ody</u>			
1.	Is Chain of C	sustody complete?	Yes 🗸	No \square	Not Present
2.	How was the	sample delivered?	Client		
<u>Log</u>	<u>In</u>				
3.	Coolers are p	present?	Yes 🗸	No 🗌	na 🗆
4.	Shipping con	tainer/cooler in good condition?	Yes 🗸	No \square	
5.		ls present on shipping container/cooler? nments for Custody Seals not intact)	Yes	No \square	Not Required 🗹
6.	Was an atter	mpt made to cool the samples?	Yes	No 🗸	NA \square
			Bulk material.		
7.	Were all item	ns received at a temperature of >0°C to 10.0°C*	Yes	No 🗌	NA 🗹
8.	Sample(s) in	proper container(s)?	Yes 🗸	No 🗆	
9.	Sufficient sar	mple volume for indicated test(s)?	Yes 🗸	No \square	
10.	Are samples	properly preserved?	Yes 🗸	No \square	
11.	Was preserv	ative added to bottles?	Yes	No 🗸	NA 🗌
12.	Is there head	Ispace in the VOA vials?	Yes	No 🗆	NA 🗹
13.	Did all sampl	es containers arrive in good condition(unbroken)?	Yes 🗸	No \square	
14.	Does paperw	ork match bottle labels?	Yes 🗸	No 🗌	
15.	Are matrices	correctly identified on Chain of Custody?	Yes	No 🗸	
16.	Is it clear what	at analyses were requested?	Yes 🗸	No 🗌	
17.	Were all hold	ling times able to be met?	Yes 🗸	No \square	
<u>Spe</u>	cial Handl	ing (if applicable)			
-		otified of all discrepancies with this order?	Yes	No 🗌	NA 🗸
	Person	Notified: Date			
	By Who	om: Via:	eMail Pho	one 🗌 Fax	☐ In Person
	Regard	ing:			
	Client Ir	nstructions:			

19. Additional remarks:

Item Information

* Note: DoD/ELAP and TNI require items to be received at 4°C +/- 2°C

Seattle, WA 98103 Seat	CAN ALTO		0 Fremont			CI	na	in (of (Cu	sto	dy	Re	cor	d	& L	ab	ora	ato	ry Services Ag	reement	
Fax: 206-352-7128 Project Name: NVL Labs, Inc. Project No: 2012-494 Collected by: Seattle, WA, 98103 Location: Amorphise: 206-805-6412 Report To [PM]: Marcus Gladden Marcus g@nvllabs.com PM Email: Marcus g@nvllabs.com PM Email: Sample Disposal by lab (after 30 days) Marcus g@nvllabs.com PM Email: Sample Name Sample Disposal by lab (after 30 days) Sample Name Sample Disposal by lab (after 30 days) Sample Name Sample Disposal by lab (after 30 days) Sample Name Sample Disposal by lab (after 30 days) Sample Name Sample Disposal by lab (after 30 days) Marcus g@nvllabs.com PM Email: Namicus g@nvllabs.com Namicus g@nvllabs.com PM Email: Namicus g@nvllabs.com PM Email: Namicus g@nvllabs.com PM Email: Namicus g@nvllabs.com Namicus g@nv	Fremor				Date	01		Line of the same										Lab	orator	y Project No (internal):	5135	
NYL Labs, Inc.		Ref A	ax: 206-35	2-7178				Rain	ier (Com	mon							Spe	cial Re	marks:		
Address 4708 Aurora Ave N Collected by: Dave Leonard	NVL Labs. Inc.				2012-494																	
Seartile WA 98103	Client:				Proje	CT NO:		Dave	ماد	ona	rd											
	Address:				Collected by:										-							
Sample Name Sample Date Time (Matrix)* Sample Time (Matrix)* Sample Sample Time (Matrix)* Sample Sample Time (Matrix)* Sample Sample Time (Matrix)* Sample Sa	206-805-6412				Location:												. 🗆	Discount househ (after 20 days	-1			
Sample Sample Sample Date Time (Matrix)* Comments Didg 13- e. elev-ground- #44-3-4 split Didg 13- e. elev-ground- #44-3-4 split Comments Didg 13- e. elev-ground- #44-3-4 split Didg 13- e. elev-ground- #44-3					Repo	rt To (PI	M):	Mar	cus	Gla	adde	en						San	nple Di	sposal: Return to client	Disposal by lab (after 50 day)	')
Sample Date Sample Type	Fax:				PM E	mail:		mar	cus	.g@	nvl	labs	s.coi	m								
31119-13EG-44SPLIT 03/11/19 09:30								/	/	/	14	HOD	SOF /	/	/	100	///	//	//	////		
31119-13EG-44SPLIT 03/11/19 09:30						,	30	//	/,	Paris	Mail	Se cle	(3)	W 00	100	1200	//	//	//			
31119-13EG-44SPLIT 03/11/19 09:30				Sample		100	3/	/	23/180	000	The last	8 27 C	270	80° (E)	A O		3/	//	//			
31119-13EG-44SPLIT 03/11/19 09:30				Туре	10	2 16	4/4	Casolii .	e Holo	o lesell		NE SE	100 N	etals	T ACIE	10 Ja	//	//	//		Comments	
RL of <1 PPM OESIACO				(IVIatrix)		7	Ť	Ť	T	Ť	T	1			1		1			bldg 13- e. elev-grou	ind- #44-3-4 split	
OESIRCO OUTUBER OUT	1 31113-1320 4401 211						1		1			<u> </u>										T,
OESIRCO OUTUBER OUT	2								-	+								+				
OESIRCO OUTUBER OUT	3						+		+									+	+	101 of 11 00	m	4
	4						+		+		+	+			+	+						
	5						+	-	-	+	+	-			-		-		+	VESTICAL		
	6						-		+	-		-			-		+	+				
	7						1		-					4	1	-		-			<u> </u>	
	8																		-			
	9								1													
Matrix: A = Air, AQ = Aqueous, B = Bulk, O = Other, P = Product, S = Soil, SD = Sediment, SL = Solid, W = Water, DW = Drinking Water, GW = Ground Water, SW = Storm Water, WW = Waste Water	10																				T - 1-	
	*Matrix: A = Air, AQ = Aqueous, B = Bulk, O	= Other, P = P	roduct, S =	Soil, SD =	Sedime	nt, SL =	Solic	i, W=	Wate	r, DW	= Drin	king W	/ater,	GW = G	round	Water	, SW =	= Storr	n Wate	er, WW = Waste Water	Turn-arouna Time:	
	**Metals (Circle):					70.01			1-1												Standard	
I represent that I am authorized to enter into this Agreement with Fremont Analytical on behalf of the thent named above and that I have verified Client's agreement to									-					med a	bove	and t	hat I	have	verif	ied Client's agreement to	3 Day	
each of the terms on the front and backside of this Agreement.	each of the terms on the front and	backside of t	this Agree	ment.	FICE	nont A	mary	ical	on D	chail	1	F	/	-	20,0						2 Day	
Relinquished Date/Time Received Date/Time	Relinquished	Date/Tin	ne			_	:	Receive	d/	M	T				D			1/1	a	1010		
7/9/C 16-93	x Relinquished	S/II	19	16'	45			Receive	d	/					D	e		(/ ((157)		
Relinquished Date/Time Same Day Same Day x	X	Jucy III															1				The state of the s	_



April 19, 2019

Shimon Mizrahi Rainier Commons LLC 918 S. Horton Street, Suite 1018 Seattle, WA 98134

Subject: Polychlorinated Biphenyl (PCB) Substrate Testing

SANDSTONE - POST VISUAL CLEARANCE

Site Address: Rainier Commons, LLC

3100 Airport Way S, Seattle, WA

NVL Project#: 2012-494

Dear Mr. Mizrahi:

Per your request, NVL Laboratories Inc. (NVL) tested sandstone substrate, following final visual clearance and approval of paint removal work, for the presence of Polychlorinated Biphenyls (PCBs), at the Rainier Commons site per the conditions for such testing pursuant to Condition 8 of the EPA's December 18, 2013 Risk Based Disposal Approval for Rainier Commons. The purpose being to collect and provide data sufficient for the EPA to conclude that the visual performance standard is adequate to verify both removal of the PCB bulk waste and that when the visual clearance performance standard is met no further clean-up is likely required of the remaining substrate, with any remaining detectable levels of PCBs registering below the threshold for unrestricted use.

EXECUTIVE SUMMARY

Utilizing the "Sample Location Selection" process delineated in the Rainier Sampling Plan for Verification of Concrete Substrate Once Visual Clearance Standard Met (the NVL Substrate Sampling Plan), NVL randomly selected representative locations of the sandstone substrate. These randomly selected locations were then tested for the presence of PCBs, after all paint abatement work was completed and after all work areas were cleared utilizing the visual clearance performance standard and procedures.

Laboratory analysis of the sandstone substrate did not detect the presence of PCBs with a Reporting Limit of less than 1 ppm. The results confirm that the visual clearance standards already approved for brick and mortar are also effective for sandstone substrates. The results further confirm that PCBs contained in the historical layers of paint applied to the sandstone did not migrate into the sandstone substrate. These findings meet the requirements of Condition 8 of the EPA's Risk Based Disposal Approval (RBDA) for Rainier Commons.

Based on the findings, it is recommended that Rainier Commons request modification to the RBDA to eliminate sandstone substrate sampling requirements, effective upon the completion of the Phase I work.

BACKGROUND

Condition 8 of the EPA's Risk Based Disposal Approval for Rainier Commons requires testing of



each type of substrate, from which historical layers of paint have been removed, to determine if PCBs contained in the paint migrated into the substrate, or remain at greater than 1 ppm following visual clearance pursuant to the visual clearance performance standards applicable to the work as set forth in Condition 7 of the RBDA and Exhibit 12 of the Phase I Individual Phased Work Plan (Phase 1 IPWP). Substrate test results confirm whether or not the visual clearance performance standard is sufficient to clear that particular type of substrate and can be relied upon, without further additional destructive substrate testing, to clear that particular type of substrate for unrestricted use. That is to say the substrate does not contain PCBs greater than 1 ppm.

The approved NVL Substrate Sampling Plan requires that a Certified Industrial Hygienist (CIH) oversee all sample collection, analysis, data interpretation and reporting with regards to substrate testing. After reviewing results for samples collected to date during the Phase I work on Buildings 10, 11 and 13, it became apparent that a CIH had not been involved in all aspects of all sample planning and collection events. The purpose of some Phase I samples previously collected was to assess abatement techniques and later collected samples were initially intended to serve as post-clearance samples. The timing of work performed, sample collection, punchlist work and the vernacular of "pre-clearance" and "post-clearance" samples apparently caused some confusion upon initial review of NVL's reporting on the laboratory results for these previously collected samples. Additionally, due to the piece meal approach in the initial series of sample collection events, the Field QA/QC procedures described in the NVL sampling plan were not adequately addressed. Given this, Rainier Commons determined to initiate the collection of a new sandstone substrate sample set, commissioning NVL's CIH to prepare the sampling plan, oversee all sample location identification, collection, analysis, data interpretation and reporting, including all field QA/QC requirements. The body of this report provides the details of the sandstone substrate sampling that was performed March 22, 2019 in response to this request.


Earlier sampling events – not included in this report but previously reported upon to EPA - and their purpose included the following:

- Rainer Commons requested the collection and analysis of sandstone substrate samples
 from Building 10/11 on October 9, 2014, prior to the visual clearance of the Phase I work, to
 measure the efficacy of initial sandblasting efforts. These informational pre-clearance
 samples were used to better understand the performance of the initial sandblasting
 techniques employed at that time and were not intended as "clearance" samples.
- On December 1, 2014 a sandstone substrate sample was obtained by NVL Laboratory personnel for the purpose of addressing Condition 8 of the RBDA. The field samples were obtained utilizing the "Sample Collection" section of the approved NVL Substrate Sampling Plan.
- During a subsequent desk review of the EPA SOP for Sampling Porous Surfaces for PCBs, it was noted that the document requires that the sampled area be cleaned with a clean brush or cloth prior to drilling (Section 9.1.1). This procedural step had been omitted in the NVL Substrate Sampling Plan. No specific annotation regarding proper sample site preparation was included in the field notes, therefore, it was concluded that areas where previous testing had identified the slight presence of PCBs, additional substrate sampling was warranted to ensure the required preparation step in the EPA SOP was performed.



SITE MAP

The circled area on this site map shows the locations of buildings 10 and 11 at Rainier Commons.



METHOD

Field collection and subsequent laboratory analysis was performed in accordance with the NVL *Substrate Sampling Plan* (Exhibit 11 to Phase 1 IPWP), revised to include and match the EPA SOP.

Details in NVL's Substrate Sampling Plan included:

- Having a Certified Industrial Hygienist (CIH) overseeing all sample collection, analysis, data interpretation and reporting involved with this assessment
- Specific procedures to randomly select sample testing locations
- Specific protocol for identifying the samples
- Specific instructions for sample collection
- Field QA/QC procedures, which included collecting field duplicate and split samples
- Specific requirements for the laboratories selected for sample analysis

The laboratories selected for sample analysis were:

- NVL Laboratories. Inc.
- Fremont Analytical Inc.

Both are accredited laboratories for analysis for PCB Aroclor content via EPA Method 8082. A Reporting Limit of less than 1 ppm was requested at the time of sample submission consistent with the requirements of the RBDA and unrestricted use.




TESTING

NVL, with Dave Leonard CIH on-site, conducted the testing on March 22, 2019 to test for PCBs. This substrate sampling was conducted following the conclusion of all Phase I work to remove PCB-containing paint coatings from the building and following the approval of all Phase I paint removal work by both NVL and the owner.


SAMPLE LOCATION SELECTION

The sample location selection protocol identified in NVL's *Substrate Sampling Plan* involved using a grid system. The following details how the grid pattern was established for Buildings 10 and 11 where the sandstone substrate was located.



Once the grid pattern and the 30 grid locations were identified, in order to define a smaller area to sample (the larger grid size being appropriate to the visual clearance sampling but not necessary or appropriate for gathering substrate material), the sampling grid was then further divided into four Sub-Grids (15"X15") (Sub-Grids), and each of the Sub-Grids was again divided into four more smaller Sub-Sub-Grids (7.5"x7.5").

The following table graphically shows how any Grid was further divided into a Sub-Grid and into a Sub-Sub-Grid along with numbering designation system:



Polychlorinated Biphenyl (PCB) Substrate Testing Project No. 2012-494

Page 4 / 11

SANDSTONE - POST VISUAL CLEARANCE April 19, 2019



2	Sub-Grid	Each = ~15" x ~15" Shown is the numbering designation system Highlighted is Sub-Grid #2		3	2		
3	Sub-Sub-Grid	Each = ~ 7.5" x ~7.5" Shown is the numbering designation system Highlighted is Sub-Sub-Grid #1			3	4	

Once this grid pattern system was established, the three sampling locations were selected using the random number generator at www.random.org.

After the random selection of the three sampling locations, the selection of the location for duplicate and split samples was also performed using the random number generator at www.random.org.

The following summarizes the locations identified using the random number generator:

Sample Location	Grid	Sub-Grid	Sub-Sub-Grid	QC	QC
1	26	1	2	duplicate	-
2	8	3	4	-	-
3	24	1	3	-	split

Sample identification was also made per the protocols identified in NVL's *Substrate Sampling Plan* and are indicated as follows:

Sample	Sample Location	Grid	Sub Grid	Sub-Sub Grid	Sample Identification
1	1	26	1	2	32219-10WG-26-DUPA
2	1	26	1	2	32219-10WG-26-DUPB
3	2	8	3	4	32219-10WG-8
4	3	24	1	3	32219-10WG-24-SPLITA
5	3	24	1	3	32219-10WG-24-SPLITB



SAMPLE COLLECTION

Surface debris, if any, was removed using a clean brush and cloth as described in NVL's Substrate Sampling Plan prior to drilling.

Samples were collected using an impact hammer drill with a 5/8 inch concrete drill bit to generate a uniform, finely ground powder. Depth was controlled to be no more than one half inch by marking the depth with tape on the drill bit.

The drill bit was cleaned and decontaminated before use, and after each sample was obtained per the description in the sampling plan, which included scrubbing with water containing detergent, followed by rinsing with clean water, then rinsing/wiping the surface with hexane.

Clean, previously unused disposable gloves were used at each sample location.

Two holes needed to be drilled to obtain an approximated 10 grams of material per sample.

The split sample was collected at the same time as the original sample at that location. This was achieved by drilling four holes to generate approximately 20 grams of material that was then put into a single sample container. The closed sample container was then shaken to mix the sample and then half of the contents were then put into the "split" sample container leaving approximately 10 grams of material in each container.

The field duplicate sample was a separate sample collected as close as possible to the same point as the original sample at that location. Prior to the sample being collected, the same procedures for cleaning and decontaminating the drill bit were followed.

OBSERVATIONS

The following photographs note observations made when testing occurred on March 22, 2019.



Location 26-1-2

Area located, identified and prepared for sample collection. This particular location was for duplicate samples.

Sample collected at this location: 32219-10WG-26-DUPA

Surface debris was removed using a clean brush and cloth prior to drilling.



2



Location 26-1-2

As with all locations, samples were collected using an impact hammer drill with a 5/8 inch concrete drill bit to generate a uniform, finely ground powder. Depth was controlled to be no more than one half inch by marking the depth with tape on the drill bit.

3



Cleaning Drill Bit Step 1- Soap wash

The drill bit was cleaned and decontaminated before use, and after each sample was obtained per the description in the sampling plan, which included scrubbing with water containing detergent, followed by rinsing with clean water, then rinsing/wiping the surface with hexane.

4



Cleaning Drill Bit Step 2 - Rinse

The washed drilled bit is being rinsed in a bucket with clean water.

ວ



Cleaning Drill Bit Step 3 – Hexane

The surface of the rinsed drill bit is being wiped with a clean cloth that was wetted with hexane.



6



Location 26-1-2

Area prepared to collect the field duplicate sample which was a separate QA/QC sample collected as close as possible to the original sample.

Sample collected at this location: 32219-10WG-26-DUPB

7



Location 26-1-2

To collect the field duplicate sample two holes were drilled adjacent to the previous drill holes to obtain ~10 grams of material for the single sample.

8



Location 8-3-4

Sample collected at this location: 32219-10WG-8

9



Location 8-3-4

Collecting sample 32219-10WG-8 with

an impact hammer drill with a 5/8 inch concrete drill bit with the finely ground powder dropping onto to paper below to catch the material.







Location 24-1-3

Four holes were drilled to create ~20 grams of material to create the split QA/QC samples.

Samples collected at this location: 32219-10WG-24-SPLITA 32219-10WG-24-SPLITB

SAMPLE SUBMISSION

NVL maintained exclusive custody, control and security of samples collected and relinquished them to the selected laboratories for analysis using laboratory specific Chain of Custody (COC) forms that included fields for sample identification number, parameter for analyses, sample collection date and custody transfer signatures.

Per NVL's *Substrate Sampling Plan*, samples were submitted to accredited laboratories for analysis for PCB Aroclor content via EPA Method 8082. A Reporting Limit (RL) of less than 1 ppm was requested at the time of sample submission.

The laboratories selected for sample analysis were:

- NVL Laboratories, Inc.
- Fremont Analytical Inc.

RESULTS

The following table summarizes the results for sandstone substrate testing:

SANDSTONE SUBSTRATE TESTING RESULTS Sampling Date: 3/22/19									
Sample Identification	Sample Type	Lab	Sample Grid Location #	Lab RL	Total PCBs Analytical Results (PPM)	Result More Than 1 PPM?			
32219-10WG-26- DUPA	DUP	NVL	26-1-2	0.40	0.42	NO			
32219-10WG-26- DUPB	DUP	NVL	26-1-2	0.39	ND	NO			
32219-10WG-8	-	NVL	8-3-4	0.39	ND	NO			
32219-10WG-24- SPLITA	SPLIT	NVL	24-1-3	0.38	0.41	NO			
32219-10WG-24- SPLITB	SPLIT	F	24-1-3	0.988	ND	NO			

ND = Non-Detect

Project No. 2012-494

PPM = Parts per million or milligrams per kilogram (mg/kg)

Lab RL = Laboratory Reporting Limit

N = NVL Laboratories

F = Fremont Analytical

Polychlorinated Biphenyl (PCB) Substrate Testing

SANDSTONE - POST VISUAL CLEARANCE April 19, 2019



DISCUSSION

Laboratory analysis did not detect any level of PCBs equal to or above 1 ppm in any of the samples. All samples were run with a reporting limit of less than 1 ppm. All samples results were below the requirement for unrestricted use.

Field QA/QC Procedures

Field Duplicate Samples:

- Reproducibility and representativeness of the samples was confirmed with the results of
 the field duplicate samples. The field duplicate samples were separate samples
 collected as close as possible to the same sample location and analyzed by the same
 laboratory (NVL). Analysis results for both duplicate samples did not detect the
 presence of PCBs with a reporting limit of less than 1 ppm. This meets the QA/QC
 requirement that laboratory analysis results must be within 75 to 125 percent of each
 other to be acceptable.
- A duplicate sample was taken at one of the three testing locations. In other words, 33% of the three samples taken from the three locations had a "field duplicate" which meets the QA/QC procedure criteria that a minimum of 10% of the sample set be field duplicates.

Split Samples:

- Accuracy and reproducibility of the analytical results was confirmed by the split samples.
 The analytical results of splitting a sample and having it analyzed at two separate
 laboratories (NVL Laboratories and Fremont Analytical) did not detect the presence of
 PCBs with a reporting limit of less than 1 ppm. This meets the QA/QC requirement that
 laboratory analysis results must be within 75 to 125 percent of each other for the split
 sample results to be acceptable.
- One sample from the three sample locations was identified as a Split Sample that was submitted to another laboratory for analysis. This is 33% of the sample locations and 25% of the 4 samples submitted to the same laboratory, which meets the QA/QC procedure criteria that a minimum of 5% of the sample set be split samples.

Laboratory QA/QC Procedures

 Both NVL Laboratories and Fremont Analytical followed the QA/QC procedures that are requirements of NVL's Substrate Sampling Plan which include the addition of surrogates, laboratory control sample (LCS) and LCS duplicate, matrix spike (MS) and MS duplicate and continuous calibration check (CCV) sample for all PCB analysis. All results of QA/QC procedures were within analytical protocols. Copies of the laboratory analysis are included with this report which details the QA/QC information.

CONCLUSION

Sample selection was representative of the population in that all sandstone substrate was equally considered during the random selection process. Testing of the sandstone substrate did not detect the presence of PCBs with a Reporting Limit of less than 1 ppm. The findings confirm that the visual clearance standards approved for brick and mortar are also reliable to

Polychlorinated Biphenyl (PCB) Substrate Testing Project No. 2012-494

SANDSTONE - POST VISUAL CLEARANCE

April 19, 2019



confirm and approve removal of paint from sandstone substrates and that PCBs contained in the historical layers of paint applied to the sandstone did not migrate into the sandstone substrate. These findings meet the requirements of Condition 8 of the EPA's Risk Based Work Plan Approval (RBDA) for Rainier Commons. As a result, it is recommended that Rainier Commons request modification to the RBDA to eliminate sandstone substrate sampling requirements, effective as of the completion of Phase I.

Reviewed by:

Testing & Assessment Overseen by:

Munaf Khan Project Manager

Laboratory Director / President

David Leonard MSPH, CIH Certified Industrial Hygienist Technical Resource Expert

ATTACHMENTS

Laboratory Testing Reports:

- NVL Laboratories Inc. Batch Number 1905670
- Fremont Analytical Inc. Analytical Report Work Order Number 1903329

REFERENCED

- Condition 8 of the EPA's December 18, 2013 Risk Based Disposal Approval for Rainier Commons (RBDA)
- NVL Substrate Sampling Plan (Exhibit 11 to Phase 1 IPWP), revised to include and match the EPA SOP.
- Exhibit 12 of the Phase I Individual Phased Work Plan (Phase I IPWP)
- Visual clearance standards required in Condition 7 of the RBDA and Exhibit 12 of the Phase IIPWP

March 25, 2019



Mr. Marcus Gladden NVL Field Services Division 4708 Aurora Ave. N. Seattle, 98103

Re: NVL Batch 1905670.00

Project Name/Number: 2012-494

Project location: 3100 Airport Way South Seattle, WA 98134

Dear Mr. Gladden,

Enclosed please find test results for samples submitted to our laboratory for analysis. Preparation and analysis of these samples were conducted in accordance with published industry standards and methods specified on the attached analytical report.

The content of this package consists of the following:

- -Case Narrative & Definition of Data Qualifiers
- -Analytical Test Results
- -Applicable QC Summary
- -Client Chain-of-Custody (CoC)
- -NVL Receiving Record

The report is considered highly confidential and will not be released without your approval. Samples are archived for two weeks following analysis. Samples that are not retrieved by the client will be discarded after two weeks.

Thank you for using our laboratory services. If you need further assistance, please contact us at 206-547-0100 or 1-888-NVLLABS.

Sincerely,

Nick Ly, Technical Director

Enclosure: Sample Results



Case Narrative:

The following summarizes samples received on date as shown on the accompanied Chain of custody by NVL Laboratories, Inc. from NVL Field Services Division for Project Number: 2012-494. Samples were logged in for PCB analysis per client request using both customer sample ID's and laboratory assigned ID's as listed on the Chain-of-Custody (CoC). All samples as received were processed and analyzed within specified turnaround time without any abnormalities and deviations that may affect the analytical results. All quality control requirements were acceptable unless stated otherwise. The conditions of all samples were acceptable at time of receipt and all samples submitted with this batch were analyzed unless stated otherwise on the CoC.

Test Results are reported based on dry weight in micrograms per kilograms (mg/kg) for PCB samples as shown on the analytical reports.



Definition Appendix

Terms

% Rec	Percent recovery.
<	Below Reporting Limit(RL) or Limit of Quantitation(LoQ) of the instrument.
В	Blank contamination. The recorded results is associated with a contaminated blank.
DF	Dilution Factor
J	The reported concentration is an estimated value because something may be present in the sample that interfered with the analysis.
J1	The reported concentration is an estimated value because the laboratory control sample (LCS) is out of control limits.
J2	The reported concentration is an estimated value because the percent recovery for matrix spike is out of control limits.
J3	The reported concentration is an estimated value because the relative percent difference(RPD) for duplicate analysis is out of control limits.
J4	Percent recovery is outside of established control limits.
LCS	Laboratory Control Sample.
LFS	Laboratory Fortified Spike
Limits	The upper and lower control limits for spike recoveries.
LN	Quality control sample is outside of control limits. This analyte was not detected in the sample.
LOQ	Limit of quantitation(same as RL)
mg/kg	Milligrams per kilogram.
ND	Analyte not detected or below the reporting limit of the instrument or methodology



Definition Appendix

Terms

PPM Parts per Million.

QC Batch Group Quality Control Batch Group. The entity that links analytical results

and supporting quality control results.

R The data are not reliable due to possible contamination or loss of

material during preparation or analysis. Re-sampling and reanalysis

are necessary for verification.

RL Reporting Limit. The minimum concentration that can be quantified

under routine operating conditions.

RPD Relative Percent Difference. The relative difference between

duplicate results(matrix spike, blank spike, or samples duplicate)

expressed as a percentage.

RPD Limit The maximum RPD allowed for a set of duplicate

measurements(see RPD).

SMI Surrogate has matrix interference.

Spike Conc. The measured concentration, in sample basis units, of a spiked

sample.

SURR-ND Surrogate was not detected due to matrix interference or dilution.

ug/m3 Micrograms per cubic meter.

ug/mL Micrograms per milliliter

mg/Kg milligram per kilogram

SDG Number

4708 Aurora Ave N, Seattle, WA 98103 p 206.547.0100 | f 206.634.1936 | www.nvllabs.com

ANALYSIS REPORT



Polychlorinated Biphenyls by Gas Chromatography

Client NVL Field Services Division

1905670.00

Date Reported **03/25/2019**Project Number **2012-494**

Location 3100 Airport Way South Seattle, WA 98134

Samples Received*

Analyzed By

Evelyn Ahulu

Samples Analyzed*

4

Analysis Method Preparation Method 8082A

3546PR (PCB)

* for this test only

Sample Number	32219-10WG-26-DUPA	Received	03/22/2019
Lab Sample ID	19029516	Matrix	Bulk/Dust
Initial Sample Size	5.0449 gm	Units of Result	mg/Kg, as received

Analyte	RL	Final Result	Analysis Date
Aroclor-1016	0.40	< 0.40	03/22/2019
Aroclor-1221	0.40	< 0.40	03/22/2019
Aroclor-1232	0.40	< 0.40	03/22/2019
Aroclor-1242	0.40	< 0.40	03/22/2019
Aroclor-1248	0.40	< 0.40	03/22/2019
Aroclor-1254	0.40	0.42	03/22/2019
Aroclor-1260	0.40	< 0.40	03/22/2019
PCBs, Total	0.40	0.42	

Sample Number	32219-10WG-26-DUPB	Received	03/22/2019
Lab Sample ID	19029517	Matrix	Bulk/Dust
Initial Sample Size	5.0739 gm	Units of Result	mg/Kg, as received

Analyte	RL	Final Result	Analysis Date
Aroclor-1016	0.39	< 0.39	03/22/2019
Aroclor-1221	0.39	< 0.39	03/22/2019
Aroclor-1232	0.39	< 0.39	03/22/2019
Aroclor-1242	0.39	< 0.39	03/22/2019
Aroclor-1248	0.39	< 0.39	03/22/2019
Aroclor-1254	0.39	< 0.39	03/22/2019
Aroclor-1260	0.39	< 0.39	03/22/2019
PCBs, Total	0.39	<0.39	

ANALYSIS REPORT



Polychlorinated Biphenyls by Gas Chromatography

Sample Number	32219-10WG-8	Received	03/22/2019
Lab Sample ID	19029518	Matrix	Bulk/Dust
Initial Sample Size	5.098 gm	Units of Result	mg/Kg, as received
Analyte		RL	Final Result Analysis Date
Aroclor-1016		0.39	< 0.39 03/22/2019
Aroclor-1221		0.39	< 0.39 03/22/2019
Aroclor-1232		0.39	< 0.39 03/22/2019
Aroclor-1242		0.39	< 0.39 03/22/2019
Aroclor-1248		0.39	< 0.39 03/22/2019
Aroclor-1254		0.39	< 0.39 03/22/2019
Aroclor-1260		0.39	< 0.39 03/22/2019
PCBs, Total		0.39	<0.39
Sample Number	32219-10WG-24-SplitA	Received	03/22/2019
Lab Sample ID	19029519	Matrix	Bulk/Dust
Initial Sample Size	5.2222 gm	Units of Result	mg/Kg, as received
miliai Gampio Gize	9···		3 3,
•	g	RL	Final Result Analysis Date
Analyte	3g.v.	RL 0.38	
Analyte Aroclor-1016	J		Final Result Analysis Date
Analyte Aroclor-1016 Aroclor-1221	g	0.38	Final Result Analysis Date < 0.38 03/22/2019
Analyte Aroclor-1016 Aroclor-1221 Aroclor-1232	J	0.38 0.38	Final Result Analysis Date < 0.38 03/22/2019 < 0.38 03/22/2019
Analyte Aroclor-1016 Aroclor-1221 Aroclor-1232 Aroclor-1242		0.38 0.38 0.38	Final Result Analysis Date < 0.38 03/22/2019 < 0.38 03/22/2019 < 0.38 03/22/2019
Analyte Aroclor-1016 Aroclor-1221 Aroclor-1232 Aroclor-1242 Aroclor-1248		0.38 0.38 0.38 0.38	Final Result Analysis Date < 0.38 03/22/2019 < 0.38 03/22/2019 < 0.38 03/22/2019 < 0.38 03/22/2019
Analyte Aroclor-1016 Aroclor-1221 Aroclor-1232 Aroclor-1242 Aroclor-1248 Aroclor-1254 Aroclor-1260		0.38 0.38 0.38 0.38 0.38	Final Result Analysis Date < 0.38 03/22/2019 < 0.38 03/22/2019 < 0.38 03/22/2019 < 0.38 03/22/2019 < 0.38 03/22/2019 < 0.38 03/22/2019



Quality Control Results

Project Number:	2012-494				Number: ct Manager:		905670 Iarcus Gl	adden	1	
QC Batch(es):	Q923				sis Method:	808				
QC Batch Method: Preparation Date:	3546PR (PCB) 03/22/2019			Analysis D	escription:		ychlorinat omatogra		henyls by Ga	is
Blank: MBLK-19056	70									
Analyte	Blank Result	Units	DF		RL		Control Limit			Qualifiers
Aroclor-1016	ND		1		1.0		1			Qualifiers
		mg/Kg					-			
Aroclor-1221	ND	mg/Kg	1		1.0		1			
Aroclor-1232	ND	mg/Kg	1		1.0		1			
Aroclor-1242	ND	mg/Kg	1		1.0		1			
Aroclor-1248	ND	mg/Kg	1		1.0		1			
Aroclor-1254	ND	mg/Kg	1		1.0		1			
Aroclor-1260	ND	mg/Kg	1		1.0		1			
PCBs, Total Surrogates:	ND	mg/Kg	1		1.0	% Rec	1			
Tetrachloro-m-xylene			1			75	40-140			
Decachlorobiphenyl			1			85	40-140			
Lab Control Sample:	LCS-1254-19056	70								
	Blank Spike			Spike			% Rec			
Analyte	Result	Units	DF	Conc.		% Rec	Limits			Qualifiers
Aroclor-1254 Surrogates:	21.8	mg/Kg	1	20.0		109	40-140			
Tetrachloro-m-xylene			1			91	40-140			
Decachlorobiphenyl			1			99	40-140			
Lab Control Sample:	LCS-1016+1260-	1905670								
Lab Control Sample	Duplicate: LCS Du	ıp-190567	0							
	Blank Spike			Spike						
Analyte	Result	Units	DF	Conc.		% Rec	Limits	RPD	RPD Limit	Qualifiers
Aroclor-1016	19.2	mg/Kg	1	20.0		96	40-140			
	18.2			20.0		91	40-140	5	50	
Aroclor-1260	22.1	mg/Kg	1	20.0		111	40-140			
	21.4			20.0		107	40-140	3	50	
Surrogates:										
Tetrachloro-m-xylene			1			94	40-140			
						96	40-140			
Decachlorobiphenyl			1			112	40-140			
						102	40-140			



Surrogate Recovery Summary Report

Client NVL Field Services Divis	ion		SDG Number <u>1905670</u>	
Project <u>2012-494</u>				
Customer Sample ID	Lab Sample ID	Analyte	Recovery	Limits
32219-10WG-26-DUPA	19029516	Decachlorobiphenyl	106%	40-140
32219-10WG-26-DUPA	19029516	Tetrachloro-m-xylene	94%	40-140
32219-10WG-26-DUPB	19029517	Decachlorobiphenyl	103%	40-140
32219-10WG-26-DUPB	19029517	Tetrachloro-m-xylene	97%	40-140
32219-10WG-8	19029518	Decachlorobiphenyl	112%	40-140
32219-10WG-8	19029518	Tetrachloro-m-xylene	98%	40-140
32219-10WG-24-SplitA	19029519	Decachlorobiphenyl	116%	40-140
32219-10WG-24-SplitA	19029519	Tetrachloro-m-xylene	104%	40-140
LCS Dup-1905670	LCS Dup-1905670	Decachlorobiphenyl	102%	40-140
LCS Dup-1905670	LCS Dup-1905670	Tetrachloro-m-xylene	96%	40-140
LCS-1016+1260-1905670	LCS-1016+1260-1905670	Decachlorobiphenyl	112%	40-140
LCS-1016+1260-1905670	LCS-1016+1260-1905670	Tetrachloro-m-xylene	94%	40-140
LCS-1254-1905670	LCS-1254-1905670	Decachlorobiphenyl	99%	40-140
LCS-1254-1905670	LCS-1254-1905670	Tetrachloro-m-xylene	91%	40-140
MBLK-1905670	MBLK-1905670	Decachlorobiphenyl	85%	40-140
MBLK-1905670	MBLK-1905670	Tetrachloro-m-xylene	75%	40-140

^{*} Recovery outside limits



INITIAL AND CONTINUING CALIBRATION VERIFICATION

SDG No: <u>1905670</u> Contract: <u>N/A</u>

Determination: 8082 PCB Aroclors < Material>

Run	Sample	Source	Analyzed	Analyte	True	Found	Unit	% Rec	Limits
R000916	CCV1 1016-1260	PCB_2017-1-2	03/22/2019	Aroclor-1016	5	5	ug/mL	100	80-120
		PCB_2017-1-2	03/22/2019	Aroclor-1260	5	5	ug/mL	100	80-120
	CCV1 1254	PCB_2017-1-3	03/22/2019	Aroclor-1254	5	5	ug/mL	100	80-120
	ICV 1016-1254- 1260	PCB_2017-1-4	03/22/2019	Aroclor-1016	5	5.305	ug/mL	106	85-115
		PCB_2017-1-4	03/22/2019	Aroclor-1254	5	5.419	ug/mL	108	85-115
		PCB_2017-1-4	03/22/2019	Aroclor-1260	5	5.771	ug/mL	115	85-115
	CCV2 1016-1260	PCB_2017-1-2	03/22/2019	Aroclor-1016	5	5.93	ug/mL	119	80-120
		PCB_2017-1-2	03/22/2019	Aroclor-1260	5	5.963	ug/mL	119	80-120
	CCV2 1254	PCB_2017-1-3	03/22/2019	Aroclor-1254	5	5.952	ug/mL	119	80-120

% Rec = Percent recovery

FORM PAS-RSR-1.1 Date Printed: 3/25/2019 10:08 Page 1 of 1

^{* =} Percent recovery not within control limits

ORGANICS LABORATORY SERVICES

Company	NVL Field Services Division	NVL Batch Number 1905670	.00
Address	4708 Aurora Ave. N. Seattle, WA 98103	TAT 1 Day	AH No
Project Manager	Mr. Marcus Gladden	Rush TAT Due Date 3/25/2019 Time	12:30 PM
	(206) 547-0100	Email marcus.g@nvllabs.com	
cell	(b) (6)	Fax (206) 634-1936	

Proj	ject Name/N	umber: 2012-494	Project Location: 3100	Airport Way South Seattle, WA 98134
Subc	ategory Qua	antitative analysis		
Ite	m Code ORG	G-05 M e	thod 8082 PCB Aroclors <bulk></bulk>	
То	otal Numbe	er of Samples <u>4</u>	MATERIAL STATE OF THE STATE OF	Rush Samples
17445	Lab ID	Sample ID	Description	A/R
1	19029516	32219-10WG-26-DUPA		A
2	10020517	32219-10MG-26-DURB		

	Print Name	Signature	Company	Date	Time
Sampled by	Client				
Relinquished by	Client				
Office Use Only	Print Name	Signature	Company	Date	Time
Received by	Emily Schubert		NVL	3/22/19	1230
Analyzed by	Erelyn Abuly	EAR	NVL	3/22/19	14:00
Results Called by	0				
Faxed Emailed					
Special Instructions:		**************************************			

Entered By: Emily Schubert

19029518

19029519

32219-10WG-8

32219-10WG-24-SplitA

Date: 3/22/2019

Time: 12:17 PM

1 of 1

Α

Α

4708 Aurora Ave North, Seattle, WA 98103 | p 206.547.0100 | f 206.634.1936 | www.nvllabs.com

NVL Laboratories, Inc. 4708 Aurora Ave N, Seattle, WA 98103

CHAIN of CUSTODY SAMPLE LOG

1905670

1
۳.
S

	Client NVL	_aboratories	s Inc				L Batch Numb					
	Street 4708				5	CI	ent Job Numb	11-)4			
		le, WA 9810					Total Sampl	es 4				
oiect M	anager Muna					Tur	n Around Time	□ 1 Hr [3 Days	□ 10 E	ays
	cation 3100		/ South					2 Hrs 4 Hrs		4 Days 5 Days		
-,000 = 0		e, WA 9813						The state of the s	se call for TAT	- N. C.	n 24 Hr	
							Email addre					
	Phone: (206)	447-0263	Fax: (2	206) 44	17-0299							
Asbe	estos Air	PCM (NIOSH	1 7400) L	TEM ((NIOSH 740	2)	TEM (AHERA)	TEM (EI	PA Level II)	Oth	er	
Asbe	estos Bulk	PLM (EPA/60	00/R-93/11	6) 🗌	PLM (EPA F	oint Co	unt) 🗌 PLM (EPA Gravim	etry) 🗌 TE	M BUL	<	
Mold	/Fungus 🔲	Mold Air 🗌	Mold Bulk		Rotometer	Calibra	ion					
TCLF Cr 6	Metals	E. Limit FAA (ppm) ICP (ppm) GFAA (ppb) Fiberglass	Matrix Air Filte Drinking Dust/wi Nuisanc	g water pe (Are e Dust	ea) Pain	Chips	RCRA M Arsen Bariur Cadm	ic (As)	All 8 Chromium o Lead (Pb) Mercury (Ho	(Cr	ner Met All 3 Copper Nickel (Zinc (Zr	(Cuː Ni)
.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	n of Package:	Good	Damage	ed (no s	pillage)	Severe	damage (spilla	ige)				
Seq. #	Lab ID	Client	Sample N	lumber	Comment	s						A/R
1		3221	19-16 W	G-2	6-DUPA		BLDG 10.	WEST EL	EVATION	6R0	UND	220
2		14	l1	- 2	6-DUP	3	11	И	н	11		E26
3		u	71	- 8			1(4	Fl	il	- #	8.
4		11	u	- 24	-SPLIT	A	11		И	[[~ . #	24
5												
5												
5 6												
5 6 7												
5 6 7 8												
5 6 7 8 9												
5 6 7 8 9												
5 6 7 8 9 10												
5 6 7 8 9 10 11 12												
5 6 7 8 9 10 11 12 13				di								
5 6 7 8 9 10 11 12 13 14	D	int Polou	c	ing Pol			/ Comm				Time	
5 6 7 8 9 10 11 12 13 14 15		int Below	57 men at	ian Bel	ow //		Comp	any	Da 2	ate 2 7 - 1/2	Time	
5 6 7 8 9 10 11 12 13 14 15 S	ampled by	AVELED	NARD	ian Bel	ow /		Comp	any (12405	Da 3	ate 2 2 - 4		300
5 6 7 8 9 10 11 12 13 14 15	ampled by D	AVELED	57 men at	ian Bel	ow //		NU	LLABS	Da 3	ate -2 z -1/2		30
5 6 7 8 9 10 11 12 13 14 15 Relince	ampled by 7 quished by 7 eceived by 7	AVELEO.	NARD NAPD	ian Bel	ow /		NU	LLABS VL	Da 3 3 3 9 4	ate -22-19		300
5 6 7 8 9 10 11 12 13 14 15 Screening	ampled by D quished by D eceived by T nalyzed by	AVELEO.	NARD	ian Bel	ow //	of br	NU	LLABS	Da 3: 3: 3/-3	ate -2 z -19 22 -19 22 -19 22 -19		30
5 6 7 8 9 10 11 12 13 14 15 Selino Reino Results	ampled by 7 quished by 7 eceived by 7	AVELEO.	NARD NAPD	ian Bel	ow /		NU	LLABS VL	Da 3 3 3 9 3	ate -22-19 -22-19 20 19		300



3600 Fremont Ave. N.
Seattle, WA 98103
T: (206) 352-3790
F: (206) 352-7178
info@fremontanalytical.com

NVL Labs, Inc. Marcus Gladden 4708 Aurora Ave. N. Seattle, WA 98103

RE: Rainier Commons

Work Order Number: 1903329

March 25, 2019

Attention Marcus Gladden:

Fremont Analytical, Inc. received 1 sample(s) on 3/22/2019 for the analyses presented in the following report.

Polychlorinated Biphenyls (PCB) by EPA 8082 Sample Moisture (Percent Moisture)

This report consists of the following:

- Case Narrative
- Analytical Results
- Applicable Quality Control Summary Reports
- Chain of Custody

All analyses were performed consistent with the Quality Assurance program of Fremont Analytical, Inc. Please contact the laboratory if you should have any questions about the results.

Thank you for using Fremont Analytical.

Sincerely,

Mike Ridgeway Laboratory Director

DoD/ELAP Certification #L17-135, ISO/IEC 17025:2005 ORELAP Certification: WA 100009-007 (NELAP Recognized)



Date: 03/25/2019

CLIENT: NVL Labs, Inc. Work Order Sample Summary

Project: Rainier Commons

Work Order: 1903329

Lab Sample ID Client Sample ID Date/Time Collected Date/Time Received

1903329-001 32219-10WG-24-SPLIT B 03/22/2019 10:00 AM 03/22/2019 12:15 PM



Case Narrative

WO#: **1903329**Date: **3/25/2019**

CLIENT: NVL Labs, Inc.

Project: Rainier Commons

WorkOrder Narrative:

I. SAMPLE RECEIPT:

Samples receipt information is recorded on the attached Sample Receipt Checklist.

II. GENERAL REPORTING COMMENTS:

Results are reported on a wet weight basis unless dry-weight correction is denoted in the units field on the analytical report ("mg/kg-dry" or "ug/kg-dry").

The validity of the analytical procedures for which data is reported in this analytical report is determined by the Laboratory Control Sample (LCS) and the Method Blank (MB). The LCS and the MB are processed with the samples to ensure method criteria are achieved throughout the entire analytical process.

III. ANALYSES AND EXCEPTIONS:

Exceptions associated with this report will be footnoted in the analytical results page(s) or the quality control summary page(s) and/or noted below.

Prep Sample Cleanup Comments:

1903329-001A 322095 Acid: Prep Comments for METHOD (PREP-PCB-S), SAMPLE (1903329-001A) required Acid Cleanup Procedure (Using Method No 3665A).

1903329-001A 322095 Florisil: Prep Comments for METHOD (PREP-PCB-S), SAMPLE (1903329-001A) required Florisil Cleanup Procedure (Using Method No 3620C).



Qualifiers & Acronyms

WO#: **1903329**

Date Reported: 3/25/2019

Qualifiers:

- * Flagged value is not within established control limits
- B Analyte detected in the associated Method Blank
- D Dilution was required
- E Value above quantitation range
- H Holding times for preparation or analysis exceeded
- I Analyte with an internal standard that does not meet established acceptance criteria
- J Analyte detected below Reporting Limit
- N Tentatively Identified Compound (TIC)
- Q Analyte with an initial or continuing calibration that does not meet established acceptance criteria (<20%RSD, <20% Drift or minimum RRF)
- S Spike recovery outside accepted recovery limits
- ND Not detected at the Reporting Limit
- R High relative percent difference observed

Acronyms:

%Rec - Percent Recovery

CCB - Continued Calibration Blank

CCV - Continued Calibration Verification

DF - Dilution Factor

HEM - Hexane Extractable Material

ICV - Initial Calibration Verification

LCS/LCSD - Laboratory Control Sample / Laboratory Control Sample Duplicate

MB or MBLANK - Method Blank

MDL - Method Detection Limit

MS/MSD - Matrix Spike / Matrix Spike Duplicate

PDS - Post Digestion Spike

Ref Val - Reference Value

RL - Reporting Limit

RPD - Relative Percent Difference

SD - Serial Dilution

SGT - Silica Gel Treatment

SPK - Spike

Surr - Surrogate

Original



Analytical Report

Work Order: **1903329**Date Reported: **3/25/2019**


Client: NVL Labs, Inc. Collection Date: 3/22/2019 10:00:00 AM

Project: Rainier Commons **Lab ID:** 1903329-001

Matrix: Solid

Client Sample ID: 32219-10WG-24-SPLIT B

Analyses	Result	RL	Qual	Units	DF	Da	ite Analyzed
Polychlorinated Biphenyls (PC	B) by EPA 808	<u>2</u>		Batch	ID:	23932	Analyst: IH
Aroclor 1016	ND	0.988		mg/Kg-dry	1	3/22/	/2019 5:12:53 PM
Aroclor 1221	ND	0.988		mg/Kg-dry	1	3/22/	/2019 5:12:53 PM
Aroclor 1232	ND	0.988		mg/Kg-dry	1	3/22	/2019 5:12:53 PM
Aroclor 1242	ND	0.988		mg/Kg-dry	1	3/22	/2019 5:12:53 PM
Aroclor 1248	ND	0.988		mg/Kg-dry	1	3/22	/2019 5:12:53 PM
Aroclor 1254	ND	0.988		mg/Kg-dry	1	3/22/	/2019 5:12:53 PM
Aroclor 1260	ND	0.988		mg/Kg-dry	1	3/22/	/2019 5:12:53 PM
Aroclor 1262	ND	0.988		mg/Kg-dry	1	3/22/	/2019 5:12:53 PM
Aroclor 1268	ND	0.988		mg/Kg-dry	1	3/22	/2019 5:12:53 PM
Total PCBs	ND	0.988		mg/Kg-dry	1	3/22	/2019 5:12:53 PM
Surr: Decachlorobiphenyl	55.7	30.8 - 168		%Rec	1	3/22	/2019 5:12:53 PM
Surr: Tetrachloro-m-xylene	69.8	30.3 - 157		%Rec	1	3/22/	/2019 5:12:53 PM
Sample Moisture (Percent Moi	sture)			Batch	ID:	R50250	Analyst: CO
Percent Moisture	0.792	0.500		wt%	1	3/25/	/2019 9:26:13 AM





Work Order: 1903329

QC SUMMARY REPORT

CLIENT: NVL Labs, Inc.

Polychlorinated Biphenyls (PCB) by EPA 8082

Sample ID MB-23932	SampType: MBLK			Units: mg/Kg		Prep Date	e: 3/22/2 0) 19	RunNo: 502	253	
Client ID: MBLKS	Batch ID: 23932					Analysis Date			SeqNo: 986	958	
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qua
Aroclor 1016	ND	0.100									
Aroclor 1221	ND	0.100									
Aroclor 1232	ND	0.100									
Aroclor 1242	ND	0.100									
Aroclor 1248	ND	0.100									
Aroclor 1254	ND	0.100									
Aroclor 1260	ND	0.100									
Aroclor 1262	ND	0.100									
Aroclor 1268	ND	0.100									
Total PCBs	ND	0.100									
Surr: Decachlorobiphenyl	61.3		100.0		61.3	30.8	168				
Surr: Tetrachloro-m-xylene	70.9		100.0		70.9	30.3	157				
Sample ID LCS1-23932	SampType: LCS			Units: mg/Kg		Prep Date	e: 3/22/2 0)19	RunNo: 502	253	
Client ID: LCSS	Batch ID: 23932					Analysis Date	e: 3/22/2 0	019	SeqNo: 986	959	
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qua
Aroclor 1016	1.14	0.100	2.000	0	56.8	38.5	149				
Aroclor 1260	1.09	0.100	2.000	0	54.5	35.4	154				
Surr: Decachlorobiphenyl	66.7		100.0		66.7	30.8	168				
Surr: Tetrachloro-m-xylene	77.8		100.0		77.8	30.3	157				
Sample ID LCS1D-23932	SampType: LCSD			Units: mg/Kg		Prep Date	e: 3/22/2 0)19	RunNo: 502	253	
Client ID: LCSS02	Batch ID: 23932					Analysis Date	e: 3/22/2 0	019	SeqNo: 986	960	
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qua
Aroclor 1016	1.16	0.100	2.000	0	57.8	38.5	149	1.136	1.68	20	
	1.12	0.100	2.000	0	55.8	35.4	154	1.089	2.37	20	
Aroclor 1260											
Aroclor 1260 Surr: Decachlorobiphenyl	69.1		100.0		69.1	30.8	168		0		

Original Page 6 of 10



Rainier Commons

Date: 3/25/2019

Work Order: 1903329

Project:

QC SUMMARY REPORT

CLIENT: NVL Labs, Inc.

Polychlorinated Biphenyls (PCB) by EPA 8082

Sample ID LCS1D-23932 SampType: LCSD Units: mg/Kg Prep Date: 3/22/2019 RunNo: 50253

Client ID: LCSS02 Batch ID: 23932 Analysis Date: 3/22/2019 SeqNo: 986960

Analyte Result RL SPK value SPK Ref Val %REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Sample ID LCS2-23932	2-23932 SampType: LCS			Units: mg/Kg	Units: mg/Kg Prep Date: 3/22/2019					RunNo: 50253		
Client ID: LCSS	Batch ID: 23932	Batch ID: 23932				Analysis Date: 3/22/2019				SeqNo: 986953		
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual	
Aroclor 1254	1.08	0.100	2.000	0	54.0	31.9	167					
Surr: Decachlorobiphenyl	62.8		100.0		62.8	30.8	168					
Surr: Tetrachloro-m-xylene	75.0		100.0		75.0	30.3	157					



Date: 3/25/2019

Work Order: 1903329

Analyte

QC SUMMARY REPORT

CLIENT: NVL Labs, Inc.

Sample Moisture (Percent Moisture)

Project:	Rainier Commons

 Sample ID
 1903336-002ADUP
 SampType:
 DUP

 Client ID:
 BATCH
 Batch ID:
 R50250

Result

RL

Prep Date: 3/25/2019 RunNo: 50250

SeaNo: 986904

Analysis Date: 3/25/2019 SeqNo: 986904

%REC LowLimit HighLimit RPD Ref Val

%RPD RPDLimit Qual

Percent Moisture 15.4 0.500 13.51 13.1 20

SPK value SPK Ref Val

Prep Date: 3/25/2019 Sample ID 1903340-002ADUP SampType: DUP Units: wt% RunNo: 50250 Analysis Date: 3/25/2019 Client ID: BATCH Batch ID: **R50250** SeqNo: 986909 Analyte Result RL SPK value SPK Ref Val %REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Units: wt%

Percent Moisture 24.4 0.500 24.08 1.32 20



Sample Log-In Check List

C	lient Name:	NVL				Work Order Nu	ımber: 19033	29	
Lo	ogged by:	Brianna Ba	arnes			Date Received	3/22/2	019 12:15:00 PM	
Cha	in of Cust	ody							
	Is Chain of C	-	olete?			Yes 🗸	No 🗌	Not Present	
2.	How was the	sample deliv	vered?			<u>Client</u>			
<u>Log</u>	ı İn								
	Coolers are p	resent?				Yes	No 🗸	na 🗆	
٥.	Oddicio die p	resent:				Bulk materi		14/1	
4.	Shipping con	tainer/cooler	in good condition	?		Yes 🗸	No 🗌		
5.	Custody Seal (Refer to com	ls present or nments for C	shipping contain ustody Seals not	er/cooler? intact)		Yes	No 🗌	Not Required 🗹	
6.	Was an atten	npt made to	cool the samples	?		Yes	No 🗌	NA 🗹	
7.	Were all item	s received a	t a temperature o	>0°C to 10.0°	°C*	Yes	No 🗆	NA 🗸	
8.	Sample(s) in	proper conta	ainer(s)?			Yes 🗸	No 🗌		
9.	Sufficient sar	mple volume	for indicated test	s)?		Yes 🗹	No 🗌		
10.	Are samples	properly pre	served?			Yes 🗸	No 🗌		
11.	Was preserva	ative added t	to bottles?			Yes	No 🗸	NA 🗌	
12.	Is there head	space in the	VOA vials?			Yes	No 🗌	NA 🗹	
13.	Did all sample	es container	s arrive in good co	ondition(unbrok	(en)?	Yes 🗸	No 🗌		
14.	Does paperw	ork match be	ottle labels?			Yes 🗸	No 🗌		
15.	Are matrices	correctly ide	ntified on Chain o	f Custody?		Yes 🗸	No 🗌		
16.	Is it clear wha	at analyses v	vere requested?			Yes 🗸	No 🗌		
17.	Were all hold	ling times ab	le to be met?			Yes 🗸	No 🗌		
Spe	cial Handl	ing (if app	olicable)						
_			liscrepancies with	this order?		Yes	No 🗌	NA 🗹	
	Person	Notified:			Date				
	By Who				Via:	eMail 🗌	Phone Fa	x	
	Regardi	ng:						_	
	Client In	structions:							
19.	Additional rer	marks:							
<u>Item</u>	<u>Information</u>								
		Item #		Temp °C					
	Sample			22 4					

^{*} Note: DoD/ELAP and TNI require items to be received at 4°C +/- 2°C

Page 10 of 10

RANAHIDI ———————————————————————————————————	A STATE OF THE PARTY OF THE PAR	emont Ave N.		Cha	in o	f Cu	stoc	ly Re	cor	d & I	abo	rato	ry Services Ag	reement
Fremon		e, WA 98103 206-352-3790	Date:	3/2	2/1	9		Page:	1	of:		Laborator	y Project No (internal): 902	5329
Analytica	7A Fax:	206-352-7178	Project N	ame: /	PA,	NI	EK	2 0	OMI	now	5	Special Re	marks:	
Client: NVL LABS			Project N	o: Z	201	2-	4	94						
Address: 4708 AURO	RA A	VEN	WHILE THE AMERICAN IN A STREET OF THE PARTY					EOM		RD.				
City State Zin: SEATTLE	e wy	F	Location:	31	00	AIR	POR	TW	AY.	5				
City, State, Zip: SEATTLE Telephone: 206-805-	64/2	<u>.</u>	Report To	(PM):	MAS	200	5 (SLA	SEA -DD	FN	- 14	Sample Di	sposal: Return to client	Disposal by lab (after 30 days)
Fax:	J		PM Fmail	n	IAR	CU	5, 6	,0	NV	LLA	BS.	,co	n	
rah.		Sampl		620		S. C.	Ed John		W (8)	60 120 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0				
Sample Name		mple Type	* \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	1610	35 X	Aro de la			2005			//		Comments
132219-10WG-24-5P2		00 B						X					REGUEST A	RL<1PPM
2	113 110	09 19											32219-10WG	
2														
5														
-														
5														
7														
,														
0														
10														
*Matrix: A = Air, AQ = Aqueous, B = Bulk, O = O	ther, P = Produc	t, S = Soil, SD :	= Sediment, S	SL = Solid	, W = Wa	ater, DW	= Drinkin	g Water,	GW = Gro	und Water	SW = St	orm Water	, WW = Waste Water	Turn-around Time:
**Metals (Circle): MTCA-5 RCRA-8 Prior	rity Pollutants	TAL Individ	dual: Ag Al	As B B	a Be Ca	Cd Co	Cr Cu F	e Hg K I	√lg Mn	Mo Na N	i Pb Sb	Se Sr Sr	Ti Tl U V Zn	Standard
		lfate Bron		hosphate		uoride		e+Nitrite		3 .			a citi di	3 Day
I represent that I am authorized to ent each of the terms on the front and bac			th Fremont	Analy	tical on	behalf (the C	lient nai	ned abo	ove and t	nat I ha	ve verifi	eu Chent's agreement to	2 Day
Relinquished	Date/Time				eceived	11	1			Date/Tin		,	. IC	
X / Bolinguichod	3/22/19 Date/Time	1	2:15		eceived	gea	/		<	Date/Tin	19			Next Day
Relinquished x	Date/ Time			x	cceived				r P	Saccy Till				Same Day (specify)